Volvo

Volvo Car USA LLC	Technical Journal		
Technical Journal Title		Ref. No.	
Audio or media sound syste	em, distorted sound -	TJ 36769.1.0	
upgrade to V2.13.1 SW	•		
Issuer (Dept.)		Issue Date	Status Date
Technical Service	12/18/23	1/3/24	
Car Market	Function Group		
United States and Canada	3900		
Function Description	Page		
media, navigation and com	Page 1 of 2		

Attachment

File Name	File Size
TJ36769-1.mp3	0.2311 MB
TJ36769-2.mp3	0.1737 MB

DESCRIPTION:

If the customer experiences a "distorted sound" while listening to the audio system (on any media source), then follow the advice under "Service".

For reference, listen to the attached sound files TJ 36769-1.mp3 and TJ 36769-2.mp3.

CSC Customer Symptom Codes

Code	Description
FC	Audio other/Other audio problems
FY	Speakers/Distorted sound

DTC Diagnostic Trouble Codes

Vehicle Type

Туре	Eng	Eng Desc	Sales	Body	Gear	Steer	Model Year	Plant	Chassis range	Struc Week Range
224							2023-2024		-	202220-202346
225							2023-2024		-	202220-202346
227							2023-2024		-	202220-202346
236							2022-2024		-	202122-202346
238							2022-2024		-	202122-202346
246							2022-2024		-	202122-202346
256							2023-2024		-	202220-202346
536	ED	E400V6					2021-2023		-	202037-202316
536	EH	E400V8					2024-2024		-	202317-202346
536	ER	E400V12					2024-2024		-	202317-202346
536	K9	BK9KERS					2023-2024		-	202222-202346

Туре	Eng	Eng Desc	Sales	Body	Gear	Steer	Model Year	Plant	Chassis range	Struc Week Range
536	L1	BL1KERS					2023-2024		-	202222-202346
539							2022-2024		-	202139-202346

SERVICE:

Do not replace any parts. Improved software is available from version 2.13.1 in VIDA or via OTA (Over The Air).

For software release information and timing, see VIDA - Release Notes.

If not urgent for the customer, wait for the OTA to be released to the car.

If urgent, perform a software upgrade according to TJ 31543.

Note!

Almost all cars with iCUP/Google built-in are OTA capable.

Individual cars in which the manufacturer has identified as not possible to receive OTA will have a pop-up message in VIDA with a reference to follow TJ 36139.

iCUP- Infotainment Connectivity Unit Program

Warranty claim info:

To get a warranty claim accepted for a job described in this TJ, use the corresponding VST OP number stated in this TJ.

Note that the TJ number must be stated in the repair order text.

VST Operation Number

VST Operation Number	Description
36004-2	Software control module downloading

VEHICLE REPORT:

Yes, please submit a Vehicle Report if the service solution described in this TJ has no effect. Use concern area "Vehicle Report" and sub concern area "Support not needed", use function group 3900.

This TJ has two sound files.

Page 2 of 2 2024-01-03