GLOBAL SAFETY FIELD INVESTIGATIONS DCS6778 URGENT - DISTRIBUTE IMMEDIATELY

Date: January 29, 2024

Subject: N232430460 - Special Coverage

Glow Plug – Cylinder 2

Models: 2020 Chevrolet Silverado 1500

2020 GMC Sierra 1500

Equipped with 3.0L Diesel Engine (RPO LM2)

To: All General Motors Dealers

General Motors is releasing Special Coverage N232430460 today. The total number of U.S. vehicles involved is approximately 40,000. Please see the attached bulletin for details.

Customer Letter Mailing

The customer letter mailing will begin in the near future.

Global Warranty Management (GWM)

The Applicable Warranties section on the Investigate Vehicle History (IVH) screen will be updated January 29, 2024. Please verify a VIN's involvement by checking in IVH. IVH is the best source for individual VIN inquiries.

END OF MESSAGE

GLOBAL SAFETY FIELD INVESTIGATIONS

Special Coverage

N232430460 Glow Plug - Cylinder 2



Release Date: January 2024 Revision: 00

Attention: This Special Coverage can be seen in the Applicable Warranties section in Investigate Vehicle History (IVH).

		Model Year			
Make	Model	From	То	RPO	Description
Chevrolet	Silverado 1500	2020	2020		ENGINE-DIESEL, 6 CYL, 3.0L,
GMC	Sierra 1500	2020	2020	LM2	CRI, L6, DOHC, TURBO, VGT,
					ALUM, CSS50V, VAR. 1

Involved vehicles are identified on the Applicable Warranties section in GM Global Warranty Management system. This site should always be checked to confirm vehicle involvement prior to beginning any required inspections and/or repairs.

Condition	Certain 2020 model year Chevrolet Silverado 1500 and GMC Sierra 1500 vehicles may have a condition that could cause the engine's cylinder 2 glow plug to fail. If this condition occurs, the Malfunction Indicator Lamp (Check Engine Light) will illuminate, and a diagnostic trouble code will set.
Special Coverage	This special coverage covers the condition described above for a period of 15 years or 150,000 miles (240,000 km), whichever occurs first, from the date the vehicle was originally placed in service, regardless of ownership.
	For vehicles covered by Vehicle Service Contracts, all eligible claims with repair orders on or after January 29, 2024, are covered by this special coverage and must be submitted using the labor operation codes provided with this bulletin. Claims with repair orders prior to January 29, 2024, must be submitted to the Service Contract provider.
	Vehicle owners or lessees who paid for repairs referenced in this Special Coverage ("Customers") are eligible for reimbursement of their reasonable and customary expenses in accordance with the procedures specified below. The conditional right to reimbursement is provided by GM solely in the interest of customer satisfaction and is personal to Customers. Customers may not assign and GM does not consent to any assignment of any Customer's right to submit reimbursement claims, or to receive reimbursement, or any other rights granted by this Special Coverage to any third party, including but not limited to service contract providers, and this Special Coverage is not intended to and does not confer any third party beneficiary, subrogation or contribution rights, or any other rights to reimbursement, against GM, whether in law, equity or otherwise, on any third parties.
Correction	Dealers are to replace the cylinder 2 glow plug as necessary. The repairs will be made at no charge to the customer.

Parts

Quantity	Part Name	Part No.
1	Glow Plug (Cylinder 2)	55490594
1	Throttle Body Gasket	55490568

Reminder: Parts may be removed from Retail Inventory Management (RIM). Dealers should review the affected parts to confirm RIM managed status. Parts may have quantity limiters in effect.

Warranty Information

Labor Operation	Description	Labor Time	Trans. Type	Net Item
9900875	Diagnosis Only (Diagnosis did not lead to #2 glow plug replacement)	0.3-1.0	ZREG	N/A
9900876	Glow Plug Replacement	0.7	ZREG	N/A
	Add: Diagnosis Time	0.3-1.0		
9900877	Customer Reimbursement Approved		ZREG	*
	- For USA and Canada dealers only	N/A		
9900878	Customer Reimbursement Denied – For USA dealers only	N/A	ZREG	**

^{*} For USA and Canada: Submit the dollar amount reimbursed to the Customer in Net/Reimbursement. Submit \$20.00 USD (\$25.00 CAD) administrative allowance in Net/Admin Allowance.

^{**} Submit \$10.00 administrative allowance in Net/Admin Allowance.

Special Coverage

N232430460 Glow Plug - Cylinder 2



Service Procedure

- 1. A vehicle may come in with conditions that lead to a diagnosis of glow plug replacement on Cylinder #2. These conditions may include, but are not limited to, DTCs P0672, P1339, and/or P06C6.
 - If the diagnosis DOES lead to a replacement of the #2 Cylinder Glow Plug, proceed to step 2.
 - If the diagnosis does NOT lead to a replacement of the #2 Cylinder Glow Plug, no further action is
 permitted under this special coverage field action. Inform the customer that the diagnosis up to this point
 will be covered, but any other diagnosis or repair work must be paid by the customer or a policy
 adjustment.
- 2. Replace the #2 Cylinder Glow Plug. Refer to Glow Plug Replacement Cylinder 2 in SI.

Courtesy Transportation – For USA & Canada

Courtesy transportation is available for Customers whose vehicles are involved in a product program and still within the warranty coverage period. See General Motors Service Policies and Procedures Manual for courtesy transportation program details.

Customer Notification

General Motors will notify Customers of this special coverage on their vehicle (see copy of typical Customer letter included with this bulletin).

Customer Reimbursement

Customer requests for reimbursement of previously paid repairs to correct the condition described in this bulletin are to be submitted to the dealer prior to or by February 28, 2025. See General Motors Service Policies and Procedures Manual, Product Field Action Customer Reimbursement Procedure (USA & Canada) or local Policies and Procedures, for details.

Special Coverage

N232430460 Glow Plug - Cylinder 2



February 2024

This notice applies to your vehicle, VIN: _	
Dear General Motors Customer:	

As the owner of a 2020 model year Chevrolet Silverado 1500 or GMC Sierra 1500, your satisfaction with our product is very important to us.

This letter is intended to make you aware that some 2020 model year Silverado 1500 and GMC Sierra 1500 vehicles, equipped with a 3.0L engine, may have a condition that could cause the engine's cylinder 2 glow plug to fail. If this condition occurs, the Malfunction Indicator Lamp (Check Engine Light) will illuminate, and a diagnostic trouble code will set.

Do not take your vehicle to your GM dealer as a result of this letter unless you believe that your vehicle has the condition as described above.

What We Have Done: General Motors is providing owners with additional protection for the condition described above. If this condition occurs on your 2020 model year Silverado 1500 or GMC Sierra 1500 within 15 years of the date your vehicle was originally placed in service or 150,000 miles (240,000 km), whichever occurs first, the condition will be repaired for you at **no charge**. Diagnosis or repair for conditions other than the condition described above is not covered under this special coverage program. For customer's vehicles already outside of the above years and/or miles, we are still offering reimbursement if the issue occurred within the years and miles stated above. Please follow the reimbursement steps below.

What You Should Do: If you believe that your vehicle has the condition described above, repairs and adjustments qualifying under this special coverage <u>must be performed by a General Motors dealer</u>. You may want to contact your GM dealer to find out how long they will need to have your vehicle so that you may schedule the appointment at a time that is convenient for you. This will also allow your dealer to order parts if they are not already in stock. Keep this letter with your other important glove box literature for future reference.

Reimbursement: If you already paid for repairs for the condition described in this letter, and those repairs were completed prior to this mailing, please complete the enclosed reimbursement form and present it to your dealer with all required documents. Working with your dealer will expedite your request, however, if this is not convenient, you may mail the completed reimbursement form and all required documents to Reimbursement Department, PO Box 33170, Detroit, MI 48232-5170. The completed form and required documents must be presented to your dealer or received by the Reimbursement Department by February 28, 2025, unless state law specifies a longer reimbursement period.

The right to submit reimbursement claims is provided by GM solely in the interest of customer satisfaction and is personal to vehicle owners and lessees who previously paid for repairs referenced in this Special Coverage ("Customers"). Customers may not assign and GM does not consent to any assignment of any Customer's right to submit reimbursement claims, or to receive reimbursement, or any other rights granted by this Special Coverage to any third party, including but not limited to service contract providers, and this Special Coverage is not intended to and does not confer any third party beneficiary, subrogation or contribution rights, or any other rights to reimbursement, against GM, whether in law, equity or otherwise, on any third parties.

If you have any questions or need any assistance, please contact your dealer or the appropriate Customer Assistance Center at the number listed below.

For the hearing or speech impaired, please contact our Customer Assistance Center using the Telecommunication Relay Service by dialing 711 then providing the appropriate Customer Assistance Center number for your vehicle.

Division	Number	Text Telephones (TTY)
Chevrolet	1-800-222-1020	711 / 1-800-833-2438
GMC	1-800-462-8782	711 / 1-800-833-2438
Puerto Rico – English	1-866-467-9700	
Puerto Rico – Español	1-866-467-9700	
Virgin Islands	1-866-467-9700	

We are sorry for any inconvenience you may experience; however, we have taken this action in the interest of your continued satisfaction with our products.

Neelie O'Connor Global Executive Director Customer Experience Operations

Enclosure N232430460