Mazda North American Operations Irvine, CA 92618-2922



REFERENCE NO: RF-24-02 DATE: 01/24/2024

SUBJECT: KJK8-32-110A Steering Gear Service Part Replacement

When placing an order for KJK8-32-110A as a service part replacement such as a collision repair, standard "over-the-counter" order, etc. The supplemental part K1Y0-32-FX8A (spring kit) must be replaced when installing the steering gear KJK8-32-110A.

MNAO will automatically add K1Y0-32-FX8A as a force shipped component when an order for KJK8-32-110A is placed. Refer to Safety Recall 6524A repair documents in MGSS for installation of the spring kit.

If KJK8-32-110A is being ordered due to steering issues based on a customer concern, please refer to <u>Safety Recall 6524A in MGSS</u> for immediate repair.

Click here to view initial dealer letter for Safety Recall 6524A.