

# Newmar Corporation

PO Box 30  
Nappanee, IN 46550



WHEN YOU KNOW THE DIFFERENCE.

RSB 608  
JAN 23, 2024

NHTSA #24V 019  
TC #2024-016

## RECALL SERVICE BULLETIN

### AFFECTED MODELS

2022 – 2023 :: Dutch Star, Mountain Aire, London Aire, Essex

### DESCRIPTION

Newmar Corporation Service Department was made aware of a Captain Chair Pedestal manufactured by Villa International that had the welds break at the pedestal-to-base plate connection. The weld breaking would cause the seat to no longer comply with FMVSS 207 and 210. Villa filed NHTSA recall # 23E098. In response, Newmar has filed NHTSA # 24V 019 and TC# 2024-016.

### ISSUE

The improper weld from the seat pedestal-to-base plate could fail in an accident, which could increase the risk of injury.

### UNITS AFFECTED

Please refer to the attached population list for unit and VIN numbers possibly affected.

### CUSTOMER ACTION

Have the seat pedestal inspected for proper welds at a Newmar authorized service center, and if found to have improper welds, a new seat pedestal will be installed to meet the compliance FMVSS 207/210 requirements.

### DEALER ACTION

Inspection of the seats in the vehicles included in the recall is necessary to identify if a replacement pedestal is required on the Villa driver and/or passenger seats. A drawing provided by Villa International is attached to help identify the potentially defective weld. If the vehicle inspection reveals that the pedestal(s) do not have the proper weld, then the pedestal(s) are required to be replaced for the affected seat(s). Inspection includes taking and submitting photo(s) of the inspected seat pedestals and their welds. If the pedestal(s) fail inspection and require replacement, the seat pedestal(s) must be returned. If you need assistance, contact your Newmar Service Account Manager.

### PARTS NEEDED (IF NEEDED)

Item Description	Newmar Part #
Seat pedestal	033715

FLAT RATE CODE: 24V 019 LABOR TIME: .1 hr. for inspection only; 1.0 hr. for inspection and replacement.

**IMPORTANT:** Please read this bulletin in its entirety prior to beginning any diagnosis or repairs.

NOTICE: Any technical information published in this bulletin is intended for use only by a qualified, Newmar-authorized service technician. Newmar is not responsible for the misuse of this information.



WHEN YOU KNOW THE DIFFERENCE

# NEWMAR CORPORATION

NEWMARCORP.COM

## IMPORTANT SAFETY RECALL NOTICE

**Date:** January 19, 2024

**Subject:** Recall Campaign NHSTA #24V-019: Incorrect Seat Pedestal Weld

---

Newmar Campaign No.: 608 RSB

This notice is sent to you as a Newmar Dealer in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act. Newmar Corporation has decided that a non-compliance, which relates to motor vehicle safety, exists in specific Newmar recreational vehicles.

### **REASON FOR THIS RECALL**

Newmar Corporation Service Department was made aware of 2022 Dutch Star Captain Chair Pedestal manufactured by Villa International that had the welds break at the pedestal to base plate connection. The weld breaking would bring the seat out of compliance with FMVSS 207 and 210.

The improper weld from the seat pedestal to base plate not meeting FMVSS 207/210 requirements could fail in an accident which could increase the risk of an injury.

Motorhomes included in this recall include:

- 2022-2023 Dutch Star Class A motorhomes.

- 2022-2023 Mountain Aire Class A motorhomes.

- 2022-2023 London Aire Class A motorhomes.

- 2022-2023 Essex Class A motorhomes.

- 2016 London Aire Class A motorhome (New seat installed in service included in population list)

### **OWNER NOTIFICATION**

Villa International will be conducting this recall in its entirety. Newmar will notify the owner by mail and instruct them to take their motorhome to an authorized service facility to have the seat pedestal inspected for proper welds and if found to have improper welds a new seat pedestal will be installed to bring the seat into compliance with FMVSS 207/210 requirements.

### **DEALER CAMPAIGN RESPONSIBILITY**

***Dealers are to provide to all customers/owner vehicles the service of completing this campaign at no charge to the customer/owner regardless of vehicle age, vehicle mileage, or ownership at the time of repair.***

**PLEASE NOTE:** Federal law requires dealers to complete this recall service before a new vehicle is delivered to the buyer or lessee. Violation of this requirement by a dealer could result in a civil penalty. Correct all vehicles in your new vehicle inventory before delivery.

## **REPAIR PROCEDURE**

Inspection of the seats in the vehicles included in the recall is necessary in order to identify if a repair is required on the Villa driver and passenger seats. A drawing provided by Villa International will be provided to help identify the defective weld. If the vehicle inspection reveals that the pedestal does have the improper weld, then the pedestal is required to be replaced for that seat.

The National Traffic and Motor Vehicle Safety Act requires that each vehicle, which is subject to a recall campaign of this type, must be satisfactorily repaired within a reasonable time after the owner has tendered it for repair. Every effort must be made to promptly schedule an appointment with each owner and to repair their vehicle as soon as possible. Vehicle owners are being notified of this recall and have been instructed to contact Newmar and/or the National Highway Traffic Safety Administration if the condition is not remedied within a reasonable time.

**If you should have any questions, please contact your service account manager direct or the Newmar service department at: 1-866-290-5371.**

Thank you for your cooperation.

Sincerely,

Newmar Corporation



## **IMPORTANT SAFETY RECALL**

**NHTSA RECALL NO. 23E098**

**DATE: 1.10.24**

**To: Newmar Corporation**

**Subject: Villa seating recall notification**

This letter was sent in accordance with the National Traffic and Motor Vehicle Safety Act. Villa International has determined that certain Newmar motor-homes equipped with Villa passenger seating fail to conform to Federal Motor Vehicle Safety Standard no. 207, "seating systems".

The safety defect involves the pedestal used on Villa ABTS driver and passenger seating where the seat assembly is attached to the pedestal and serves as an anchorage to the vehicle. On certain seat pedestals the can may be improperly welded to the mounting plate. The pedestal in the affected seat assemblies could fail in the event of a vehicular collision.

The Villa seats affected by the recall were fabricated and delivered to Newmar Corporation from April 19, 2022 through July 19, 2022. These seats were installed in Newmar, Dutch Star, Mountain Aire, London Aire, and Essex.

### **The Repair**

Inspection of the seats in the vehicles listed above is necessary in order to identify if a repair is required on Villa driver and passenger seats. Attached with this notification is a drawing to help identify the defective pedestal.

**If the vehicle inspection reveals that the pedestal does have the improper weld, then the pedestal is required to be replaced for that seat.**

Please contact Villa International at 1-888-707-7272 for information as well as replacement parts for the repair. The parts are available by faxing your part requirements to 1-562-404-7785. If there are additional questions concerning this repair please contact James Mariel at 1-574-389-8383.



**Manufacturer Responsibility**

All the unsold new vehicles in the possession of the manufacturer and subject to this recall must be inspected as well as repaired according to the Villa repair procedure before dealers or owners can take possession of the affected vehicle.

Dealers should also receive notification of this recall and are to repair the affected vehicles of this recall at no charge to the owners regardless of mileage, vehicle age, or ownership from this time forward.

Owners of the affected vehicles recently sold from a dealer inventory in which the dealer received the recall notification are to be contacted by the dealer in order to make arrangements for the repair to be completed.

This will be done by mailing the owner's notification letter accompanying the dealer and this notification.

The vehicle owners will also be instructed to contact the Newmar customer service if their dealer does not complete the repair within seven (7) days of the mutually agreed upon service date. The owners are also instructed to contact the National Highway Traffic Safety Administration if the repair does not occur within the reasonable amount of time.

In conclusion, please ensure that the Newmar vehicles affected by this recall in your inventory have been inspected and properly repaired before selling or releasing the vehicle to dealers or owners.

We at Villa International regret to have caused this inconvenience at this time.

We have taken this action to ensure the safety of your customers and the continued satisfaction of our seating products.

Sincerely,

J.G. Mariel

Villa International



Prod#	VIN Num	Year	Brand	Type	Floor	Chassis	Date In	Date Off
<b>USA Units</b>								
501249	4UZFBT6G6	2016	LA	DP	4503	FL	3/17/2015	3/25/2015
501928	4VZVU1R1	2022	LA	DP	4579	S	6/15/2022	6/22/2022
501938	4VZVU1R1	2022	LA	DP	4533	S	6/29/2022	7/15/2022
502010	4VZVU1R1	2022	LA	DP	4551	S	4/27/2022	5/4/2022
502012	4VZVU1R1	2022	LA	DP	4551	S	4/21/2022	4/28/2022
502017	4VZVU1R1	2022	LA	DP	4551	S	4/28/2022	5/5/2022
502021	4VZVU1R1	2022	LA	DP	4551	S	5/9/2022	5/17/2022
502022	4VZVU1R1	2022	LA	DP	4551	S	6/2/2022	6/14/2022
502023	4VZVU1R1	2022	LA	DP	4533	S	5/31/2022	6/9/2022
502024	4VZVU1R1	2022	LA	DP	4535	S	6/14/2022	6/21/2022
502025	4VZVU1R1	2023	LA	DP	4569	S	6/20/2022	6/30/2022
609639	4UZFBHFE7	2022	DS	DP	4369	FL	5/5/2022	5/17/2022
609675	4UZFBHFE9	2022	DS	DP	4369	FL	6/16/2022	6/28/2022
609679	4UZFBHFE4	2022	DS	DP	4326	FL	6/1/2022	6/10/2022
609682	4UZFBHFE4	2022	DS	DP	4369	FL	6/15/2022	6/22/2022
609694	4UZFBHFE8	2022	DS	DP	4369	FL	5/5/2022	5/17/2022
609700	4UZFBHFE5	2022	DS	DP	4310	FL	5/17/2022	5/24/2022
609703	4VZAU1D1	2022	DS	DP	4369	S	6/1/2022	6/9/2022
609715	4UZFBHFE1	2022	DS	DP	4310	FL	5/24/2022	6/3/2022
609719	4UZFBHFE0	2022	DS	DP	4081	FL	5/17/2022	5/24/2022
609725	4VZAU1D1	2022	DS	DP	4369	S	6/7/2022	6/16/2022
609727	4VZAU1D1	2022	DS	DP	4369	S	6/7/2022	6/15/2022
609730	4VZAU1D1	2022	DS	DP	4081	S	5/5/2022	5/13/2022
609731	4VZAU1D1	2022	DS	DP	4081	S	7/13/2022	7/21/2022
609743	4VZAU1D1	2022	DS	DP	4369	S	6/14/2022	6/21/2022
609744	4VZAU1D1	2022	DS	DP	4369	S	6/1/2022	6/9/2022
609748	4VZAU1D1	2022	DS	DP	4369	S	5/2/2022	5/11/2022
609752	4VZAU1D1	2022	DS	DP	4081	S	5/31/2022	6/9/2022
609791	4VZAU1D1	2022	DS	DP	4369	S	5/2/2022	5/10/2022
609803	4UZFBHFE4	2022	DS	DP	4081	FL	7/12/2022	7/19/2022
609858	4UZFBHFE5	2022	DS	DP	4369	FL	6/28/2022	7/14/2022
609875	4VZAU1D1	2022	DS	DP	4369	S	7/12/2022	7/19/2022
609885	4UZFBHFE3	2022	DS	DP	4369	FL	5/20/2022	6/2/2022
609917	4VZAU1D1	2022	DS	DP	4369	S	6/3/2022	6/15/2022
609922	4VZAU1D1	2022	DS	DP	4081	S	7/12/2022	7/20/2022
609923	4VZAU1D1	2022	DS	DP	4081	S	4/29/2022	5/10/2022
609924	4UZFBHFE2	2022	DS	DP	4081	FL	5/13/2022	5/24/2022
609926	4VZAU1D1	2022	DS	DP	4081	S	5/4/2022	5/13/2022
609927	4UZFBHFE3	2022	DS	DP	4328	FL	6/10/2022	6/21/2022
609966	4VZAU1D1	2022	DS	DP	4081	S	5/13/2022	5/23/2022
610017	4UZFBHFE2	2022	DS	DP	4081	FL	6/10/2022	6/20/2022
610025	4UZFBHFE4	2022	DS	DP	4020	FL	4/27/2022	5/4/2022
610030	4UZFBHFE8	2022	DS	DP	4081	FL	4/26/2022	5/4/2022
610032	4UZFBHFE0	2022	DS	DP	4081	FL	4/26/2022	5/4/2022

Prod#	VIN Num	Year	Brand	Type	Floor	Chassis	Date In	Date Off
610033	4UZFCHFE0	2022	DS	DP	4081	FL	6/22/2022	7/12/2022
610035	4UZFCHFE0	2022	DS	DP	4369	FL	5/31/2022	6/8/2022
610037	4UZFCHFE0	2022	DS	DP	4081	FL	6/22/2022	7/12/2022
610056	4UZFCHFE2	2022	DS	DP	4081	FL	5/12/2022	5/20/2022
610057	4VZAU1D1	2022	DS	DP	4081	S	5/3/2022	5/12/2022
610062	4VZAU1D1	2022	DS	DP	4020	S	6/9/2022	6/20/2022
610091	4UZFCHFE2	2022	DS	DP	4081	FL	5/3/2022	5/12/2022
610093	4UZFCHFE7	2022	DS	DP	4081	FL	5/12/2022	5/20/2022
610097	4VZAU1D1	2022	DS	DP	4369	S	5/31/2022	6/8/2022
610105	4VZAU1D1	2022	DS	DP	4369	S	4/11/2022	4/22/2022
610115	4VZAU1D1	2022	DS	DP	4081	S	5/4/2022	5/12/2022
610129	4UZACHFE:	2022	DS	DP	3709	FL	6/10/2022	6/20/2022
610147	4UZFCHFE0	2022	DS	DP	4369	FL	6/22/2022	7/12/2022
610148	4UZFCHFE0	2022	DS	DP	4369	FL	7/14/2022	7/21/2022
610149	4UZFCHFE>	2022	DS	DP	4081	FL	4/27/2022	5/5/2022
610150	4UZFCHFE9	2022	DS	DP	4081	FL	5/20/2022	6/1/2022
610155	4UZFCHFE>	2022	DS	DP	4369	FL	7/14/2022	7/25/2022
610176	4UZFCHFE>	2022	DS	DP	4081	FL	6/10/2022	6/20/2022
610181	4UZFCHFE2	2022	DS	DP	4081	FL	4/29/2022	5/9/2022
610182	4UZFCHFE9	2022	DS	DP	4081	FL	4/27/2022	5/4/2022
610184	4UZFCHFE0	2022	DS	DP	4369	FL	4/29/2022	5/9/2022
610188	4UZFCHFE9	2022	DS	DP	4081	FL	5/19/2022	6/1/2022
610202	4VZAU1D1	2022	DS	DP	4081	S	5/18/2022	5/31/2022
610214	4UZFCHFE0	2022	DS	DP	4369	FL	5/19/2022	5/31/2022
610215	4UZFCHFE>	2022	DS	DP	4369	FL	6/9/2022	6/17/2022
610219	4VZAU1D1	2022	DS	DP	4081	S	5/11/2022	5/20/2022
610222	4VZAU1D1	2022	DS	DP	4081	S	5/11/2022	5/19/2022
610225	4UZFCHFE7	2022	DS	DP	4081	FL	5/18/2022	5/25/2022
610227	4UZACHFE:	2022	DS	DP	3736	FL	5/11/2022	5/20/2022
610229	4UZFCHFE0	2022	DS	DP	4081	FL	4/26/2022	5/3/2022
610231	4UZFCHFE0	2022	DS	DP	4369	FL	6/2/2022	6/14/2022
610235	4VZAU1D1	2022	DS	DP	4369	S	4/25/2022	5/3/2022
610237	4VZAU1D1	2022	DS	DP	4081	S	5/3/2022	5/12/2022
610238	4VZAU1D1	2022	DS	DP	4081	S	7/14/2022	7/21/2022
610239	4UZFCHFE5	2022	DS	DP	4081	FL	6/29/2022	7/15/2022
610240	4UZFCHFE3	2022	DS	DP	4081	FL	6/8/2022	6/17/2022
610241	4UZFCHFE5	2022	DS	DP	4081	FL	4/19/2022	4/27/2022
610247	4VZAU1D1	2022	DS	DP	4369	S	4/25/2022	5/3/2022
610248	4VZAU1D1	2022	DS	DP	4369	S	5/11/2022	5/19/2022
610255	4UZFCHFE0	2022	DS	DP	4369	FL	6/16/2022	6/23/2022
610286	4UZFCHFE2	2022	DS	DP	4020	FL	4/25/2022	5/2/2022
610299	4VZAU1D1	2022	DS	DP	4369	S	6/8/2022	6/17/2022
610300	4VZAU1D1	2022	DS	DP	4369	S	5/10/2022	5/19/2022
610304	4VZAU1D1	2022	DS	DP	4369	S	5/10/2022	5/18/2022
610316	4UZFCHFE4	2022	DS	DP	4369	FL	6/21/2022	7/12/2022

Prod#	VIN Num	Year	Brand	Type	Floor	Chassis	Date In	Date Off
610324	4VZAU1D1	2022	DS	DP	4328	S	6/8/2022	6/16/2022
610328	4VZAU1D1	2022	DS	DP	4369	S	6/2/2022	6/10/2022
610346	4UZFCHFE2	2022	DS	DP	4369	FL	6/15/2022	6/22/2022
610353	4UZFCHFE2	2022	DS	DP	4369	FL	6/28/2022	7/15/2022
610355	4UZFCHFE9	2022	DS	DP	4081	FL	5/3/2022	5/12/2022
610375	4UZFCHFE1	2022	DS	DP	4081	FL	7/18/2022	7/26/2022
610376	4VZAU1D1	2022	DS	DP	4081	S	7/15/2022	7/25/2022
610377	4UZFCHFE1	2022	DS	DP	4081	FL	7/13/2022	7/20/2022
610525	4UZFCHFE6	2022	DS	DP	4369	FL	4/28/2022	5/9/2022
610550	4UZFCHFE7	2022	DS	DP	4369	FL	4/28/2022	5/5/2022
610563	4VZAU1D1	2022	DS	DP	4081	S	5/9/2022	5/17/2022
610564	4VZAU1D1	2022	DS	DP	4081	S	7/12/2022	7/20/2022
610565	4UZFCHFE4	2022	DS	DP	4081	FL	6/21/2022	6/30/2022
610566	4UZFCHFE>	2022	DS	DP	4081	FL	6/20/2022	6/29/2022
610567	4VZAU1D1	2022	DS	DP	4081	S	5/17/2022	5/25/2022
610568	4UZFCHFE2	2022	DS	DP	4081	FL	6/28/2022	7/14/2022
610592	4UZFCHFE9	2022	DS	DP	4326	FL	5/12/2022	5/23/2022
610596	4UZFCHFE0	2022	DS	DP	4081	FL	5/9/2022	5/17/2022
610598	4UZFCHFE9	2022	DS	DP	4369	FL	5/13/2022	5/23/2022
610605	4UZACHFE!	2022	DS	DP	3736	FL	5/20/2022	6/1/2022
610606	4UZFCHFE1	2022	DS	DP	4369	FL	5/2/2022	5/11/2022
610608	4VZAU1D1	2022	DS	DP	4369	S	5/17/2022	5/24/2022
610611	4VZAU1D1	2022	DS	DP	4081	S	5/25/2022	6/7/2022
610613	4VZAU1D1	2022	DS	DP	4081	S	5/24/2022	6/7/2022
610614	4VZAU1D1	2022	DS	DP	4081	S	5/24/2022	6/3/2022
610615	4VZAU1D1	2022	DS	DP	4081	S	6/2/2022	6/10/2022
610616	4VZAU1D1	2022	DS	DP	4081	S	5/24/2022	6/3/2022
610617	4VZAU1D1	2022	DS	DP	4081	S	5/23/2022	6/3/2022
610618	4VZAU1D1	2022	DS	DP	4081	S	6/1/2022	6/10/2022
610619	4VZAU1D1	2022	DS	DP	4081	S	5/23/2022	6/2/2022
610620	4VZAU1D1	2022	DS	DP	4081	S	5/23/2022	6/2/2022
610621	4VZAU1D1	2022	DS	DP	4081	S	5/23/2022	6/2/2022
610622	4VZAU1D1	2022	DS	DP	4081	S	6/3/2022	6/15/2022
610623	4UZFCHFE4	2022	DS	DP	4326	FL	5/20/2022	6/2/2022
610624	4VZAU1D1	2022	DS	DP	4081	S	5/12/2022	5/23/2022
610625	4UZFCHFE6	2022	DS	DP	4081	FL	7/12/2022	7/19/2022
610626	4UZFCHFE0	2022	DS	DP	4081	FL	6/3/2022	6/14/2022
610628	4VZAU1D1	2022	DS	DP	4081	S	6/8/2022	6/16/2022
610630	4UZACHFE0	2022	DS	DP	3709	FL	6/7/2022	6/15/2022
610631	4VZAU1D1	2022	DS	DP	4081	S	7/15/2022	7/26/2022
610632	4VZAU1D1	2022	DS	DP	4369	S	6/20/2022	6/29/2022
610633	4VZAU1D1	2022	DS	DP	4081	S	6/10/2022	6/21/2022
610634	4VZAU1D1	2022	DS	DP	4369	S	6/30/2022	7/19/2022
610635	4VZAU1D1	2023	DS	DP	4328	S	6/17/2022	6/29/2022
610636	4VZAU1D1	2023	DS	DP	4369	S	6/17/2022	6/28/2022

Prod#	VIN Num	Year	Brand	Type	Floor	Chassis	Date In	Date Off
610637	4VZAU1D1	2023	DS	DP	4081	S	7/15/2022	7/26/2022
610638	4UZFCHE6	2022	DS	DP	4326	FL	6/22/2022	7/13/2022
801466	4VZVU1R1	2022	EX	DP	4569	S	6/16/2022	6/23/2022
801494	4VZVU1R1	2022	EX	DP	4551	S	4/25/2022	5/2/2022
801512	4VZVU1R1	2022	EX	DP	4551	S	4/29/2022	5/9/2022
801513	4VZVU1R1	2022	EX	DP	4551	S	6/22/2022	7/12/2022
801514	4VZVU1R1	2022	EX	DP	4569	S	5/19/2022	5/31/2022
801516	4VZVU1R1	2022	EX	DP	4551	S	5/13/2022	5/24/2022
801519	4VZVU1R1	2022	EX	DP	4551	S	5/11/2022	5/20/2022
801521	4VZVU1R1	2022	EX	DP	4551	S	5/4/2022	5/12/2022
801525	4VZVU1R1	2022	EX	DP	4551	S	5/25/2022	6/7/2022
801526	4VZVU1R1	2022	EX	DP	4551	S	6/3/2022	6/14/2022
801527	4VZVU1R1	2022	EX	DP	4569	S	6/10/2022	6/21/2022
801530	4VZVU1R1	2023	EX	DP	4595	S	7/13/2022	7/20/2022
801552	4VZVU1R1	2023	EX	DP	4595	S	7/19/2022	7/27/2022
904928	4VZVU1E1	2022	MA	DP	4118	S	6/20/2022	6/29/2022
904985	4VZVU1E1	2022	MA	DP	4118	S	6/30/2022	7/19/2022
905014	4VZVU1E1	2022	MA	DP	4118	S	5/2/2022	5/10/2022
905018	4VZVU1E9	2022	MA	DP	4543	S	4/25/2022	5/2/2022
905020	4VZVU1E1	2022	MA	DP	4118	S	5/5/2022	5/13/2022
905023	4VZVU1E1	2022	MA	DP	4118	S	5/24/2022	6/3/2022
905024	4VZAU1D1	2022	MA	DP	4118	S	5/25/2022	6/8/2022
905025	4VZVU1E1	2022	MA	DP	4118	S	6/1/2022	6/10/2022
905026	4VZVU1E9	2022	MA	DP	4551	S	6/7/2022	6/16/2022
905027	4VZVU1E1	2022	MA	DP	4551	S	6/23/2022	7/13/2022
905028	4VZVU1E1	2023	MA	DP	4118	S	6/21/2022	6/30/2022

Prod#	VIN Num	Year	Brand	Type	Floor	Chassis	Date In	Date Off
<b>CANADIAN UNITS</b>								
501899	4VZVU1R1	2022	LA	DP	4551	S	5/2/2022	5/11/2022
501920	4VZVU1R1	2022	LA	DP	4551	S	6/30/2022	7/18/2022
609925	4UZFCHE9	2022	DS	DP	4081	FL	5/12/2022	5/20/2022
610302	4VZAU1D1	2022	DS	DP	4369	S	5/10/2022	5/19/2022
610310	4VZAU1D1	2022	DS	DP	4369	S	6/15/2022	6/23/2022
610361	4VZAU1D1	2022	DS	DP	4081	S	5/9/2022	5/18/2022
610364	4UZFCHE5	2022	DS	DP	4081	FL	5/3/2022	5/11/2022
610365	4UZFCHE0	2022	DS	DP	4081	FL	5/25/2022	6/7/2022
610603	4UZACHFE	2022	DS	DP	3717	FL	6/3/2022	6/14/2022
610629	4VZAU1D1	2022	DS	DP	4081	S	6/7/2022	6/16/2022