

34-095 - M579 Hood Harness

1/22/2024

 [Edit](#)  [Clone](#)

34-095

Dimensions have been released to trim the radiator recirculation shield to alleviate a rub to the hood harness. This bulletin will provide those dimensions

and instructions for trimming the shield.

Subject

34-095 – M579 Hood Harness

Whats New Abstract

Fix As Fail – Dimensions and instructions are available for trimming the radiator recirculation shields to alleviate possible rub to the hood harness.

Condition

Dimensions have been released to trim the radiator recirculation shield to alleviate possible rub to the hood harness.

Chassis Affected

Model 579 chassis built from 4/26/2021 through 3/12/2023.

Action

Fix-As-Fail

If a customer comes into your dealership and demonstrates the condition above, trim the radiator recirculation shield to alleviate a possible rub.

Warranty

Through Standard Warranty or any applicable active Extended Warranty, Peterbilt will pay for parts at dealer net plus applicable mark-up and labor:

- **0.4 hours** labor to trim the radiator recirculation shield. Use Recommended Repair **34-095**.
- For extraordinary circumstances please use code **34-095**, add from “Recommended Repairs”, and then select the gear icon to edit Parts/Labor/Misc.
- File warranty claim within 7 days per warranty policy.

PRWS CLAIM CODING			
Campaign Code:	34-095	Campaign Type	Field Repair
Claim Category:	Truck	Repair Type	Fix-As-Fail
Customer Concern Code	169	Causal Code	44
Corrective Action Code	13	Responsibility Code:	Camp

Failure Location	042-002-072	Causal Part	NR042001
Supplier Code	N/A	SRT Code	B23-009 0.4 hours labor for: Trimming Radiator Recirculation Shield

Parts

The part is the dimension template shown in the Procedure Section below.

Quantity	Part Number	Description
1	F31-1283-0000000_F_1	Attached Dimension Template

Procedure

Please follow your dealership's safety procedures and precautions to ensure the vehicle can be safely repaired and maintained.

Please see the repair procedure in the Links section of this bulletin.

Attachments

-  [34-095 Dimension Template](#)
-  [34-095 Radiator Recirculation Shield Repair Procedure](#)