



RETAILER BULLETIN

NAS23.12.001

Please review bulletin NAS23.12.001 detailing potential manufacturing issue with AJ126 engines.

All engines in-stock should be returned to JLR, please submit a Faulty Return on RPOS and return to your facing PDC.

Any engines that are about to be installed or already installed, please open a TA with ATTN Steven Bautista. A specific procedure will be provided that must be followed before start-up / quality test.

For questions, please contact David Woods, dwoods4@jaguarlandrover.com.

20 – December - 2023			BULLETIN NO: NAS23.12.001			DEPT: CUSTOMER SERVICE						
AUDIENCE:	DEALER PRINCIPAL	X	SALES MGR	X	SALES GUIDES	X	SERVICE MGR	X	TECHS	X	PARTS STAFF	X
	GENERAL MANAGER	X	BUSINESS MGR	X	OFFICE MGR	X	SERVICE ADVISORS	X	PARTS MGR	X	WARRANTY	X
SUBJECT: AJ126 Engine Return												

After recent inspections at the Desford distribution center a potential manufacturing issue with the AJ126 engine has been identified. The latest direction from the supplier is to return all AJ126 engines for rework, so please check your local inventory for any impacted engines and submit a Faulty Return on RPOS for return to your facing PDC. A list of impacted part numbers is below:

- LR080286
- LR172357
- LR079612
- T4A11683E
- AJ813712

*Please note any part supersession number which may not be on the above list is also impacted.

New, reworked engines have been made available with a limited number en-route to the NA market. For more information please contact David Woods, dwoods4@jaguarlandrover.com, or the JLR Parts Technical Team at JLRPARTSTECH@jaguarlandrover.com.