

## UPDATE PRIOR TO SALE N856 – FRONT DRIVESHAFT NOT FULLY ENGAGED

UPDATE PRIOR TO SALE N856 – FRONT DRIVESHAFT NOT FULLY ENGAGED	
AFFECTED MODELS	24MY Range Rover and Range Rover Sport
VOLUME AFFECTED	US 9075 CAN 936
REPAIR	A concern has been identified on certain vehicles where the front driveshaft may not be fully engaged to the front differential. Requires removal of an undertray and an inspection of the front driveshaft to differential engagement, with full installation of driveshaft if needed.
REPAIR TIME	0.8 hrs + DIDO
CAMPAIGN LAUNCH	January 8 <sup>th</sup> , 2024.
NOTES	Please refer to the warranty portal to identify affected vehicles which must not be sold or delivered until the repair has been completed.