



Bulletin No.: PIT6105

Published date: N/A


Preliminary Information

PIT6105 LCDD Data Provisioning Message On Replacement Radio

Proactive

Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Cadillac	LYRIQ	2023 - 2024	All	All	All	All
Cadillac	XT4	2024	All	All	All	All
Chevrolet	Blazer EV	2024	All	All	All	All
Chevrolet	Colorado	2023	All	All	All	All
Chevrolet	Silverado EV	2024	All	All	All	All
GMC	Canyon	2023	All	All	All	All

Involved Region or Country	North America
Additional Options (RPO)	IVD
Condition	<p>When installing a replacement radio, the technician may notice the LCDD Data Provisioning message.</p> 
Cause	Radio software anomaly

Correction:

Before performing USB programming and SPS programming, press "Start" on the radio display.

After it completes, proceed with published Service Information programming for the A11 Radio.

Version History

Version	1
Modified	01/04/2024 - Created On.



GENERAL MOTORS

© 2024 General Motors. All Rights Reserved.