



Preliminary Information

PIT6074A Auxiliary Battery Not Charging

Product Investigation Review Required

Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Chevrolet	Silverado 2500HD/3500HD	2024	All	All	All	All
GMC	Sierra 2500HD/3500HD	2024	All	All	All	All

The following diagnosis might be helpful if the vehicle exhibits the symptom(s) described in this PI.

Involved Region or Country	North America
Additional Options (RPO)	Auxiliary Battery RPO K4Z
Condition	Some customers may comment that the Auxiliary Battery is not charging.
Cause	BCM Calibration issue not energizing the Auxiliary Battery relay.

Correction:

To correct this concern reprogram the BCM with the latest calibrations currently available in SPS/TLC.

Warranty Information

For vehicles repaired under the Bumper-to-Bumper coverage (Canada Base Warranty coverage), use the following labor operation. Reference the Applicable Warranties section of Investigate Vehicle History (IVH) for coverage information.

Labor Operation	Description	Labor Time
2810215	Body Control Module Reprogramming with SPS	Use Published Time

Version History

Version	2
Modified	10/11/2023 - Created on. 01/11/2024 - Updated to add correction information



GENERAL MOTORS