




Preliminary Information

PIT6105A LCDD Data Provisioning Message On Replacement Radio

Proactive

Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Cadillac	LYRIQ	2023 - 2024	All	All	All	All
Cadillac	XT4	2024	All	All	All	All
Chevrolet	Blazer EV	2024	All	All	All	All
Chevrolet	Colorado	2023	All	All	All	All
Chevrolet	Silverado EV	2024	All	All	All	All
GMC	Canyon	2023	All	All	All	All

Involved Region or Country	North America
Additional Options (RPO)	IVD and IVE
Condition	<p>When installing a replacement radio, the technician may notice the LCDD Data Provisioning message.</p> 
Cause	Radio software anomaly

Correction:

Before performing USB programming and SPS programming, press "Start" on the radio display.

After it completes, proceed with published Service Information programming for the A11 Radio.

Warranty Information

For vehicles repaired under the Bumper-to-Bumper coverage (Canada Base Warranty coverage), use the following labor operation. Reference the Applicable Warranties section of Investigate Vehicle History (IVH) for coverage information.

Labor Operation	Description	Labor Time
3486008	Perform LCDD Data Provisioning on radio	0.2 Hr.
*This is a unique Labor Operation for Bulletin use only.		

Version History

Version	2
Modified	01/04/2024 - Created On. 01/17/2024 - Updated for labor op and added IVE RPO.



© 2024 General Motors. All Rights Reserved.