

Published date: 01/30/2024

Preliminary Information

PIT6119 Minor / Auxiliary Tailgate Does Not Release

<u>Models</u>

Brand:	Model:		Model Years:	VIN:		Enginet	Transmissions:		
Di di lu.				from	to	Engine:	Transmissions.		
Chevrolet	Silverado All		2021 - 2024	All	All	All	All		
GMC	Sierra All		2019 - 2024	All	All	All	All		
Involved Region or Country North America									
Additional Options (RPO) QK2 - N		QK2 - M	- Multifunction Tailgate						
			e customers may comment that the minor/auxiliary tailgate does not open. The or/main tailgate will open with no issues.						

	The cause of this concern could be a device, added to the vehicle, that inhibits the
Cause	minor tailgate from opening when it detects a trailer hitch installed into the receiver,
	example shown below.





Correction:

These devices are not factory installed and before any in depth diagnostics are performed, they should be removed to see if the issue is resolved.

Warranty Information

Issues caused by these aftermarket devices would not be covered under warranty.

Additional SI Keywords

inop inoperative open multi multipro multiflex

Version History

Version	1
Modified	01/30/2024 - Created on.



~	-		-	-			M	\sim	-	\sim	-	~
C +	-	P.J	-	ю.	0					()	- NC	×.
~				n.	~	. Basel		\sim		\sim	5	~

© 2024 General Motors. All Rights Reserved.