



Preliminary Information

PIT6121 Replacement Frontview Camera Module Will Not Complete Learn Procedure and DTCs B101D SYM39 / B101D SYM3C Setting After Camera Replacement

Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Cadillac	Escalade	2017	All	All	All	All
Chevrolet	Silverado 1500	2017	All	All	All	All
Chevrolet	Suburban	2017	All	All	All	All
Chevrolet	Tahoe	2017	All	All	All	All
GMC	Sierra 1500	2017	All	All	All	All
GMC	Yukon	2017	All	All	All	All

Involved Region or Country	North America
Additional Options (RPO)	UEU - FORWARD COLLISION ALERT
Condition	A dealer may find that after installing Frontview Camera P/N 85667173 that the learn procedure will not complete and DTC's B101D SYM39 / B101D SYM3C are set.
Cause	SPS programming issue

Correction:

Contact Techline Customer Support Center for programming assistance as a VCI may be required to correct the concern.

Version History

Version	1
Modified	01/31/2024 - Created on.



GENERAL MOTORS