- Subject: Engineering Information Information on Selective Battery Pack Replacement for Analysis
- Attention: Proceed with this EI ONLY if the PIE number is listed in the Global Warranty Management / Investigate History link (GWM/IVH). If the EI does not show in GWM/IVH, disregard the PIE and proceed with diagnostics found in published service information. THIS IS NOT A RECALL. Refer to the latest version of Service Bulletin 04-00-89-053 for more details on the use of Engineering Information bulletins.

This EI has been revised to add the Silverado EV and HUMMER EV Pickup models and update the Correction and Warranty Information. Please discard PIE0753B.

Brand:	Model:	Model Year:		VIN Breakpoint:		Engine:	Transmission:
		from	to	from	to		
BrightDrop	EV600	2022	2022	—	_	_	_
	Zevo 600	2023	2023				
Cadillac	LYRIQ	2023	2024				
Chevrolet	Blazer EV	2024					
	Bolt EUV	2022	2023				
	Bolt EV	2017					
	Silverado EV	2024	2024				
GMC	HUMMER EV	2022	2023				
	HUMMER EV Pickup	2024	2024				
	HUMMER EV SUV						

Involved Region or Country	U.S. and Canada Dealers ONLY
Condition	GM recovers a small number of electric vehicle battery packs from customer-owned vehicles in the field each year for further engineering study and analysis. This program helps GM improve future EV products, analyze the performance of the battery packs in customer driven EVs, and proactively identify and correct potential issues before they can impact battery or vehicle performance. GM selects batteries for participation in this program based on various engineering criteria, including manufacturing data, vehicle location, vehicle mileage, and battery charging behavior. The customers involved will be contacted proactively by GM to visit a GM EV certified dealer for a battery pack replacement under warranty.

Correction

Important: Service agents must comply with all International, Federal, State, Provincial, and/or Local laws applicable to the activities it performs under this bulletin, including but not limited to handling, deploying, preparing, classifying, packaging, marking, labeling, and shipping dangerous goods. In the event of a conflict between the procedures set forth in this bulletin and the laws that apply to your dealership, you must follow those applicable laws.

Important: This technical service bulletin (TSB) can only be completed by certified repair facilities who have met all specific training, tool and equipment requirements pertaining to the vehicle Brand and Model serviced. Repairs must be performed by a technician who has successfully completed the required training.

If you have been contacted by GM Engineering and/or the customer with the above concern, perform the following:

1. Verify that this **PIE0753** appears in IVH for this vehicle's VIN.

2. Verify the warranty coverage.

If the vehicle does not have active high voltage battery warranty, DO NOT proceed with this El.

- 3. Contact GM Technical Assistance (TAC) to start a case and reference PIE0753 to pre-authorize the battery pack replacement.
 - U.S. dealers should contact TAC via Dealer Case Management (DCM).
 - Canada dealers should contact TAC at the 800 numbers provided (refer to GM Canada Service Policies & Procedures Manual) after the vehicle arrives at the Dealer.
- 4. Follow the appropriate document below to complete the battery order with the Battery Service Center (Spiers New Technologies or Labelmaster in U.S. and York Electronics in Canada). Reference **PIE0753** when ordering.
 - Bolt EUV and Bolt EV 19-NA-194
 - HUMMER EV/HUMMER EV SUV/BrightDrop/Silverado EV latest version of 23-NA-202
 - LYRIQ 23-NA-217
 - Blazer EV 23-NA-217

Important: The high voltage battery pack should be replaced following published SI procedures (Drive Motor Battery Replacement and Shipping Preparation).

- 5. PRIOR to proceeding with battery removal, determine if any hazards exist. If any of these conditions exist, contact TAC **BEFORE** proceeding with removal.
 - Bolt EUV / Bolt EV If coolant/water is inside the battery pack. Refer to the High Voltage System Inspection document in SI and follow steps for Battery Coolant Level Low.
 - HUMMER EV/HUMMER EV SUV/Brightdrop/Silverado EV/Lyriq/Blazer EV Follow 23-NA-151
- 6. Record all DTCs present in any module on the repair order then follow published service procedures to replace the High Voltage Battery pack.
- 7. Follow published procedures to prepare the removed battery for return shipping:
 - Bolt EUV and Bolt EV Drive Motor Battery Replacement and Shipping Preparation
 - HUMMER EV/HUMMER EV SUV/BrightDrop/Silverado EV 22-NA-005: Information on Opening / Closure Instructions for DDR and Hybrid/Electric Vehicle Battery Pack Replacement and Shipping Preparation
 - LYRIQ and Blazer EV Hybrid/Electric Vehicle Battery Pack Replacement and Shipping Preparation
- 8. Follow the core return process outlined in one of the bulletins/PIs below:
 - Bolt EUV and Bolt EV 19-NA-194
 - HUMMER EV/HUMMER EV SUV/BrightDrop/Silverado EV 23-NA-202
 - LYRIQ 23-NA-217
 - Blazer EV **23-NA-217**

If DTCs are set or additional customer concerns are noted on the RO, proceed with diagnosis and repair using the published service procedures found in SI for those concerns.

Warranty Information

For vehicles repaired per this EI and under the EV Limited Component Warranty, use the following appropriate labor operation. Reference the Applicable Warranties section of Investigate Vehicle History (IVH) for coverage information.

Labor Operation	Description	Labor Time			
5080368*	Engineering Information - Information on Selective Battery Pack Replacement for Analysis	0.2 hr			
5031030	Drive Motor Battery Replacement and Shipping Preparation – Engineering Investigation – Bolt EV/EUV only	Use Published Labor Operation Time			
5031630	Hybrid/Electric Vehicle Battery Pack Replacement and Shipping Preparation – BrightDrop, Silverado EV, Hummer, LYRIQ or Blazer EV				
*This is a unique Labor Operation for bulletin use only					

This is a unique Labor Operation for bulletin use only.

Version	4
Modified	Released May 31, 2023 Revised September 28, 2023 – including Canada Dealers, added the 2024 LYRIQ and Blazer EV, updated the Correction section and added Labelmaster to step 4. Revised October 02, 2023 – Updated steps 3 and 4. Revised January 25, 2024 – Added the Silverado EV and HUMMER EV Pickup models and updated the Correction and Warranty Information.