



SSM 52228 2023 F-150 - 3.5L PowerBoost - Intermittent No Start And Stop Safely Now Message Displayed And/Or DTCs U0293 And/Or P1A43 In The Battery Energy Control Module (BECM) - Built On Or After 3-Nov-2023

Some 2023 F-150 equipped with a 3.5L PowerBoost engine built on or after 3-Nov-2023 may exhibit an intermittent no start and Stop Safely Now message displayed in the instrument panel cluster (IPC) and/or diagnostic trouble codes (DTC) U0293 and/or P1A43 in the BECM or in connected vehicle data. A gateway module A (GWM) software concern may be triggering the no start condition. This does not affect vehicle durability and no additional diagnosis or service is required for this condition at this time. Inform customers that the vehicle will start after leaving it off temporarily. Engineering is currently working on a solution for this condition that is expected in March 2024. Monitor OASIS for additional information.