

Repair Available – <u>Service Action 87H9 / Pressure & Temperature Sensors</u>

This notice is for:	All Dealer Personnel				
Date:	February 12, 2024				
Issue:	On vehicles manufactured within a specific period, the pressure and temperature sensors in the air conditioning system may fail. If this happens, the air conditioning system will no longer function.				
Repair:	 REPAIR AVAILABLE – February 13, 2024 - Inspect and, if necessary, replace the affected pressure & temperature sensors See ELSA and Service References in Elsa2Go for complete repair & claiming instructions. Check daily campaign open inventory report or OMD for affected vehicles in inventory Repair every affected inventory vehicle <u>before delivery to consumers</u>. 				
Parts Department:	Parts will be managed by Free Order.				
Affected Vehicles	Country	Beginning Model Year	Ending Model Year	Vehicle	Vehicle Count
Affected Vehicles	Country USA			Vehicle E-TRON QUATTRO	
Affected Vehicles		Model Year	Year		Count
Affected Vehicles	USA	Model Year 2021	Year 2022	E-TRON QUATTRO E-TRON SPORTBACK	Count 7,387
Affected Vehicles	USA USA	Model Year 2021 2020	Year 2022 2022	E-TRON QUATTRO E-TRON SPORTBACK QUATTRO	Count 7,387 3,307

-END OF MESSAGE-

Ensure all dealership personnel are aware of this notice so they are able to address customer questions. Contact Warranty if you require additional assistance. Direct press inquiries to Audi Public Relations.