

		Tesla, Inc. Service Bulletin		<i>Retrofit Updated Rear Steering Actuator</i>					
SB-24-32-004 January 23, 2023									
Classification				Section/Group		Mobile Service		Configuration	
Campaign Bulletin				32 - Steering		Cannot Perform		All	
Model Year		Model		Country/Region		Build Location			
2024		Cybertruck		United States		Giga Austin			
The model(s) and model year(s) listed are a general approximation of the affected VIN list. Refer to the VIN/Bulletin Tracker or Customer/Vehicle profile to determine applicability of this bulletin for a particular vehicle.									

Campaign Bulletin: This campaign bulletin addresses a non-safety-related condition and provides recommended technical diagnosis and repair procedures. Apply this procedure to the applicable vehicles.

Condition

For the Cybertruck, an updated rear steering actuator that provides a tighter turning radius is available for retrofit. The previous rear steering actuator does not affect or impact vehicle safety or reliability. The updated part is for product enhancement.

Correction

Retrofit the vehicle with an updated rear steering actuator.

 **NOTE:** If this bulletin is applicable to the vehicle, perform the correction without any need for inspection.

Correction Description	Correction	Time
SB-24-32-004 Not Applicable	S012432004	0.00
Retrofit Updated Rear Steering Actuator	S022432004	1.68

	Part Number	Description	Quantity
Parts Required	1250851-00-D	REAR STEERING ACTUATOR	1
	1051373-00-A	VOSS 203 – 6mm CONNECTOR	1

These part numbers were current at the time of publication. Use the revisions listed or later, unless otherwise specified in the [Parts Catalog](#).

Shop Supplies Cable ties

Procedure

1. Replace the rear steering actuator with the updated component (refer to Service Manual procedure [3201099022](#)).
2. Check the vehicle 4 wheel alignment and adjust if necessary (refer to Service Manual procedure [31002300](#)).