

Seal, Weather Trim Strip (B-Pillar Trim) on Rear Doors Detaching

Topic number	LI72.12-P-076175
Version	3
Function group	72.12 - Rear door
Date	2/22/24
Validity	MODEL 206 206.0 FIN "F" up to manufacturing date: Jan. 18, 2023 206.0 FIN "R" up to manufacturing date: Feb. 23, 2023
Reason for change	Remedy update

Complaint

Seal, B-pillar trim on rear doors cracked in upper area, see picture 1.

Attachments	
File	Description
Bild 1.jpg	



Cause

Production deviation at supplier of B-pillar trim.

Remedy

Replace B-pillar trim through optimized parts.

Note:

In the event of a problem on only one door, the trim molding of the B-pillar should also be replaced on the other door.

WIS-References

Document number	Title	Note
AR72.12-P-1713WT	Remove/install front trim strip from window frame of rear door	

Symptoms

Body > Door/Flap > Door > Door > Seal cracked/torn

Body > Door/Flap > Door > Trim > Loose

XENTRY Tips

Parts						
Part number	ES1	ES2	Designation	Quantity	Note	EPC
A2066907504			Outer left B-pillar trim molding	1		X
A2066907604			Outer right B-pillar trim molding	1		X

Operation numbers/damage codes				
Op. no.	Operation text	Time	Damage code	Note