



Technical Service Bulletin

GROUP

BODY

NUMBER

24-BD-001G

DATE

FEBRUARY 2024

MODEL(S)

ALL

SUBJECT:

PROPER REMOVAL OF WINDSHIELD WIPER BLADE
PROTECTIVE COVER

Description: This bulletin contains information about the proper removal of the windshield wiper blade protective cover on all models. If the protective cover is not removed correctly, there is a possibility of the rubber insert and rail spring becoming partially separated on the inner side of the wiper blade, which could lead to poor wiping performance and/or possible scratching of the windshield glass. Follow the procedure in this bulletin to properly remove the windshield wiper blade protective cover on all new wiper blades.



Example of Protective Cover: Passenger Side



Example of Protective Cover: Driver Side



Applicable Vehicles:

- All Models

Warranty Information:


Normal warranty applies.

Circulate To: General Manager, Service Manager, Parts Manager, Warranty Manager, Service Advisors, Technicians, Body Shop Manager, Fleet Repair

Service Procedure:

1. To correctly remove the windshield wiper blade protective cover:
Slightly lift the wiper blade, then remove the cover in the direction of the arrows shown at right.
2. After removing the protective cover, check to see if the rubber insert or rail spring are separated.

Correct Removal:



NOTICE

Do not pull down on the protective cover. See examples of incorrect removal results below.

Incorrect Removal:



Examples of incorrect removal results:

