

## ISSUE H467/N857 – PCM CIRCUIT BOARD INCORRECT ASSEMBLY

### UPDATE PRIOR TO SALE H467/N857 – POWERTRAIN CONTROL MODULE BOARD INCORRECT ASSEMBLY

AFFECTED MODELS	24MY Range Rover Velar 24MY F-PACE and XF
VOLUME AFFECTED	Land Rover US 14 CAN 3 Jaguar US 24 CAN 1
REPAIR	A concern has been identified where the Powertrain Control Module (PCM) has been assembled to an incorrect specification. This can lead to electrical shorts inside the PCM. Replacement of the PCM is required
REPAIR TIME	0.5 hrs. + DIDO
CAMPAIGN LAUNCH	UPS quarantine notice issued on January 12th, 2024 Repair bulletin publication pending parts supply. Expected late February
NOTES	7 affected Range Rover Velar vehicles are in new unsold retailer inventory. These vehicles must not be retailed until repaired. The balance of the affected population will be held and repaired in the ports of entry. Please refer to the warranty portal to identify affected vehicles which must not be sold or delivered until the repair has been completed.