

## UPS H467/N857 – PCM CIRCUIT BOARD INCORRECT ASSEMBLY

UPDATE PRIOR TO SALE H467/N857 – POWERTRAIN CONTROL MODULE BOARD INCORRECT ASSEMBLY	
AFFECTED MODELS	24MY Range Rover Velar 24MY F-PACE and XF
VOLUME AFFECTED	Land Rover US 14 CAN 3 Jaguar US 24 CAN 1
REPAIR	A concern has been identified where the Powertrain Control Module (PCM) has been assembled to an incorrect specification. This can lead to electrical shorts inside the PCM. Replacement of the PCM is required
REPAIR TIME	0.5 hrs. + DIDO
CAMPAIGN LAUNCH	UPS quarantine notice issued on January 12th, 2024 Repair bulletin pending parts supply. Forecast late Feb availability.
NOTES	As of February 1st, 2024, there are 7 new Range Rover Velar vehicles in unsold retailer inventory, these cannot be retailed until repaired. Please refer to the warranty portal to identify affected vehicles which must not be sold or delivered until the repair has been completed.