

## THERMOSTAT INSPECTION REQUEST - LR117568 & AJ814048

### Customer Voice:

- After thermostat replacement, the instrument cluster says that the engine is overheating while driving.

### Technical Description:

- A manufacturing issue with thermostats LR117568 and AJ814048 has been identified.

### Status:

- Units produced after February 2023 should be quarantined and returned to JLR.
- Please inspect your local inventory for any LR117568 or AJ814048 thermostats produced after February 2023 and submit a Faulty Return on RPOS for return to your facing PDC..
- Please see the image for an example of the date code stamping. Note the photo shows a thermostat that should be returned. stamping is in European format; DD-MM-YYYY.

Refer to BULLETIN NO: NAS24.01.001 / JLRCS-2401.01

#### Discovery

- 17 -20MY Discovery

#### Jaguar

- 17-20MY F-PACE
- 16-20MY XF
- 16-19MY XE

#### Range Rover

- 15-19MY Range Rover
- 15-19MY RR Sport
- 18-20MY RR Velar

