Audi On-car analysis list from March, 5 2024

Please contact Audi Helpline before attempting repair

All topics have associated worksheets to be filled out and attached to the TAC ticket. Worksheets can be found at: Elsa2Go>>Service References>> Search v4p

|  | Models                                    | MY            | Engine       | Trans | Торіс   | Topic details  |
|--|---|---------------|--------------|-------|---|--|
|  | Q3  | 2020-<br>2021 | All          | All   | Coolant warning<br>Lamp   | Customer states they receive a low coolant waning in the cluster. Coolant level appears to be full in the reservoir  |
|  |   |               |              |       |   | Case does not relate to TSB 2061918<br>Photo showing reservoir level   |
|  | A6, A7, Q8,<br>Q7, S4, S5                 | 2019-<br>2023 | 3.0<br>EA839 | All   | Catalytic converter   | P042000: Catalyst System,Bank1 Efficiency Below<br>•©FF Log with all fault codes and completed test plans.<br>•©IN-4-Pin Worksheet with answers to questions<br>•Bequested pictures, see Questions/ Steps in worksheet |
|  | Q4 e-tron                                 | 2022-<br>2024 | All          | All   | Charging cable<br>cannot be removed<br>from the vehicle                 | See e-tron charging questionnaire worksheet  |
|  | Q3  | 2021-<br>2024 | all          | all   | P008700 - Low fuel<br>pressure  | MIL on with DTC P008700 Low fuel pressure<br>Fill out worksheet<br>Delivery rate test needed   |
|  | e-tron Q and<br>SB<br>Q8 e-tron<br>and SB | 2019-<br>2024 | All          | All   | Vehicle cannot be<br>charged, charge<br>socket lock without<br>function | See e-tron charging questionnaire worksheet  |
|  | Q7, Q8                                    | 2017-<br>2019 | All          | All   | Corrosion on<br>wheelhouse cover<br>plate                               | 2017-2019 Q7<br>2019 Q8<br>Various photos and inspections, see worksheet.  |
|  | e-tron GT                                 | 2022-<br>2024 | All          | All   | Front side window inoperative   | Customer concern that a front door module function is<br>inoperative<br>water test, inspect door harness and pillar connection   |
|  | e-tron<br>Quattro<br>e-tron SB            | 2023-<br>2024 | Any          | Any   | Noise from Front<br>Door Trim Panel                                     | Noise from front door trim panel while driving<br>Video of noise before repair is performed<br>Photos of repair  |
|  | Q5  | 2022          | Any          | Any   | Q5 Temp sensor  | DTC P218500<br>Various photos of surrounding area<br>See worksheet   |
|  | A5  | 2023-<br>2024 | Any          | Any   | Noise from Front<br>Door speaker Grill                                  | Noise from front door trim panel while driving<br>Video of noise before repair is performed<br>Photos of repair  |