



Preliminary Information

PIT6125 Code U166A Set After a Programming Event

Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Chevrolet	Blazer EV	2024	All	All	All	All

Involved Region or Country	North America
Condition	After a programming event, U166A Loss of Communication with the K56U Special Purpose Vehicle Control Module may be set as a Current code in the B174W Frontview Camera – Windshield module.
Cause	Calibration

Correction:

If U166A is found disregard it.
 U166A will not cause any vehicle concerns.
 U166A will be corrected in a future software update.
 This PI will be updated when software is available.

Version History

Version	1
Modified	02/05/2024 - Created on.

