



Preliminary Information

PIC6483A Loss of EBCM/Brake System Control Module Communication U1610 and/or U1639 Setting

Product Investigation Review Required

Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Cadillac	LYRIQ	2023	All	All	All	All

Involved Region or Country	North America
Condition	A customer may comment of one or more of the following messages: Service Brake , ABS , Suspension or Park Brake. Additionally they may comment of either a hard or soft brake pedal. There will be no warning chime. Upon inspection DTC U1610 and/or U1639 maybe set and there will be no communication with the Brake System Control Module.
Cause	Under Investigation

Correction:

Contact General Motors Technical Assistance or create a TAC case through Dealer Case Management.

Do not attempt any repairs, do not disconnect the 12 volt battery, or remove power from any modules.

Version History

Version	2
Modified	12/22/2022 - Created on. 02/06/2024 - Edited Admin details.

