



Bulletin No.: PIC6539  
Published date: 02/14/2024

# Preliminary Information

## PIC6539 Heated Steering Wheel Inoperative During Remote Start Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Buick	Encore GX	2024	All	All	All	All
Buick	Envista	2024	All	All	All	All
Chevrolet	Trailblazer	2024	All	All	All	All
Chevrolet	Trax	2024	All	All	All	All

Involved Region or Country	North America
Condition	Customer may state that the heated steering wheel is inoperative when remote starting their vehicle.
Cause	This normal operation.

### Correction:

No repair attempts should be made to correct this condition. The heated steering wheel is a standalone module and does not communicate on any CAN buses and only works when commanded on by operator using its switch.

### Version History

Version	1
Modified	02/14/2024 - Created on.



GENERAL MOTORS

© 2024 General Motors. All Rights Reserved.