



Bulletin No.: PIP5963
Published date: 02/27/2024

Preliminary Information

PIP5963 3.0L with a Crank - No Start and Setting DTC P062B

Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Chevrolet	Silverado	2024	All	All	3.0L (LZ0)	All
GMC	Sierra	2024	All	All	3.0L (LZ0)	All

Involved Region or Country:	North America
Condition:	Some customers may complain of the MIL being illuminated and the engine may crank but fail to start.
Cause:	This may be caused by a software anomaly.

Correction:

If the P062B is set and it is the first time in, clear the code and return the vehicle to the customer.

If it is the second time in with the P062B, replace the ECM.

Version History

Version	1
Modified	02/27/2024 - Created on.

