



Preliminary Information

PIP5965 3.0L Diesel Setting DTC P138C

Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Cadillac	Escalade	2023 - 2024	All	All	LM2	All
Chevrolet	Suburban	2023 - 2024	All	All	LM2	All
Chevrolet	Tahoe	2023 - 2024	All	All	LM2	All
GMC	Yukon	2023 - 2024	All	All	LM2	All
GMC	Yukon XL	2023 - 2024	All	All	LM2	All

Involved Region or Country:	North America, Europe, Kazakhstan, Uzbekistan, Middle East Israel, Palestine, Argentina, Brazil, Bolivia, Chile, Columbia, Ecuador, Paraguay, Peru, Uruguay, Japan, Cadillac Korea, Philippines, Australia/New Zealand, Other Africa
Condition:	Some customers may comment of a malfunction indicator lamp illuminated. The technician may find P138C set in the ECM.
Cause:	This may be caused by a software anomaly

Correction:

None at this time.

Engineering is aware of the concern and working on a software update.

Until the software update is released in a bulletin, do not replace the ECM or perform further diagnosis.

Clear DTC's and advise the customer a software update is forthcoming.

Warranty Information

For vehicles repaired under the Powertrain coverage, use the following labor operation. Reference the Applicable Warranties section of Investigate Vehicle History (IVH) for coverage information.

Labor Operation	Description	Labor Time
4086388	Labor Operation For P138C	0.4 Hrs.

Version History

Version	1
Modified	02/29/2024 - Created on.



GENERAL MOTORS