



## STAR ONLINE PUBLICATION



**Case Number:** S240800001

**Release Date:** January 2024

**Symptom/Vehicle Issue:** Corning Lamp, Steering Directed Head Lamp Inoperative

**Customer Complaint/Technician Observation:** The owner is inquiry on how to enable the corning lamp/steering directed head lamp option. The technician cannot locate the option within the Uconnect system.

**Discussion:** The cornering lamp feature is not available on North American (NA) built GC – Tonale or GG Hornet models. Do not replace any parts to add this feature the option is not available.

This document does not authorize warranty repairs. This communication documents a record of past experiences. STAR Online does not provide any conclusions about what is wrong with the vehicle. Rather, it captures all previous cases known that appear to be similar or related to the vehicle symptom / condition. You are the expert, and you are responsible for deciding on the appropriate course of action.

**Contact STAR Center, or your Technical Assistance Center Via TechConnect, eCONTACT or Service Library entry if no solution is found.**