

STAR ONLINE PUBLICATION
















Case Number: S2423000001

Release Date: January 2024

Symptom/Vehicle Issue: Rear Cab Silencer Trim Panel Servicing.

Discussion: Technicians may find the rear bulkhead trim panel silencer trim panel is hard to remove and or several trim clips have broken upon removal.

It has been determined the following 6 clips (red circled) shown in figure 1 are not required and can be removed from the panel when servicing or making a repair requiring removal of the rear trim panel.



Remove the 6 clips highlighted in red

Figure 1

This document does not authorize warranty repairs. This communication documents a record of past experiences. STAR Online does not provide any conclusions about what is wrong with the vehicle. Rather, it captures all previous cases known that appear to be similar or related to the vehicle symptom / condition. You are the expert, and you are responsible for deciding on the appropriate course of action.

Contact STAR Center, or your Technical Assistance Center Via TechConnect, eCONTACT or Service Library entry if no solution is found.

Stellantis US LLC Version 4.5 07/22/2022