

Technical Service Bulletin (TSB)
Rear Wheel Bearing Noise

REFERENCE:	TSB: 17-001-24 GROUP: 17 - Rear Suspension	Date:	January 5, 2024	REVISION:	17-004-23
VEHICLES AFFECTED:	2024 (B1) Jeep Renegade 2023 - 2024 (M1) Jeep Compass 2023 - 2024 (H1) Jeep Commander This bulletin applies to vehicles built on and after June 22, 2023 (MDH 0622XX) and on and before August 31, 2023 (MDH 0831XX).			MARKET APPLICABILITY:	
				<input checked="" type="checkbox"/> NA	<input type="checkbox"/> CH
				<input type="checkbox"/> EE	<input type="checkbox"/> IAP
				<input checked="" type="checkbox"/> SA	<input type="checkbox"/> MEA
CUSTOMER SYMPTOM:	The customer may notice the following: <ul style="list-style-type: none"> Rear wheel bearing noise on the right side while driving the vehicle. 				
CAUSE:	Wheel Bearing Defect.				

This bulletin supersedes Technical Service Bulletin (TSB) 17-004-23, date of issue December 05, 2023, which should be removed from your files. All revisions are highlighted with ****asterisks**** and include an updated LOP number.

This Technical Service Bulletin (TSB) has also been released as a Rapid Service Update (RSU) 23-339, date of issue December 05, 2023. All applicable RSU VINs have been loaded. To verify this RSU service action is applicable to the vehicle, use VIP or perform a VIN search in DealerCONNECT/Service Library. All repairs are reimbursable within the provisions of warranty. This RSU will expire 18 months after the date of issue.

REPAIR SUMMARY:

This bulletin involves replacing the right rear wheel bearing.

CLAIMS DATA:

Labor Operation No:	Labor Description	Skill Category	Labor Time
05-21-08-92	Rear Wheel Bearing - Replace (Right Side) (0 - Introduction)	4 - Chassis	0.7 Hrs.
Failure Code	ZZ	Service Action	

SPARE PARTS:

Qty	Part No.	Description	Notes
1	7095535 - SA 68674110AA - Mopar	Rear Wheel Bearing	Right

DIAGNOSIS:

If a customer's VIN is listed in VIP or your RSU VIN list, perform the repair. **This bulletin applies only to vehicles on the RSU VIN list.**

REPAIR PROCEDURE:

1. Replace the right rear wheel bearing. Refer to the detailed service procedures listed in DealerCONNECT>Service Library>Service info>under: 17 - Rear Suspension / Hub And Bearing / Removal and Installation.

POLICY:

Reimbursable within the provisions of the warranty.

This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of FCA US LLC.