

<b>REFERENCE:</b>	<b>TSB:</b> 23-005-24 <b>GROUP:</b> 23 - Body	<b>Date:</b>	January 19, 2024	<b>REVISION:</b>	-
<b>VEHICLES AFFECTED:</b>	<b>2022 - 2023 (BV) Jeep Renegade</b> This bulletin applies to vehicles built on or after May 02, 2022 (MDH 0502XX) and on or before November 13, 2023 (MDH 1113XX).			<b>MARKET APPLICABILITY:</b>	
				<input type="checkbox"/> NA	<input type="checkbox"/> MEA
				<input type="checkbox"/> SA	<input checked="" type="checkbox"/> IAP
				<input type="checkbox"/> EE	<input type="checkbox"/> CH
<b>CUSTOMER SYMPTOM:</b>	<b>Customers may experience the following:</b> <ul style="list-style-type: none"> <li>Missing left underbody panel</li> </ul>				
<b>CAUSE:</b>	Part missing during assembly.				

This Technical Service Bulletin (TSB) has also been released as a Rapid Service Update (RSU) 24-013, date of issue January 19, 2024. All applicable RSU VINs have been loaded. To verify this RSU service action is applicable to the vehicle, use VIP or perform a VIN search in DealerCONNECT/Service Library. All repairs are reimbursable within the provisions of warranty. This RSU will expire 18 months after the date of issue.

**REPAIR SUMMARY:**

This bulletin involves installation of the missing underbody panel.

**CLAIMS DATA:**

Labor Operation No:	Labor Description	Skill Category	Labor Time
11-50-05-9F	Panel, Underbody - Install (0 - Introduction)	6 - Electrical and Body Systems	0.2 Hrs.
Failure Code	ZZ	Service Action	

**SPARE PARTS:**


Qty	Part No.	Description	Notes
1	68254964AA	Floor Pan Shield	
2	68201478AA	Hex Nut	
3	06510891AA	Retaining button	

**DIAGNOSIS:**

If a customer's VIN is listed in VIP or your RSU VIN list, perform the repair. **This RSU only applies to vehicles on the RSU VIN list.**

## REPAIR PROCEDURE:

1. Raise vehicle on hoist. Refer to the detailed service procedures listed in DealerCONNECT Service Library under: 04 - Vehicle Quick Reference / Hoisting / Standard Procedure.
2. Install the new underside body protection.



**Fig. 1**  
Underside Body Protection

- 1 - Retaining Buttons
- 2 - Hex Nuts
- 3 - Underside Body Protection

3. Install and tighten the new nuts and install the retaining buttons.
4. Remove the vehicle from the lift.

## POLICY:

Reimbursable within the provisions of the warranty.

*This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of FCA US LLC.*