Technical Service Bulletin (TSB) PARTS & SERVICES Technical Service Bulletin (TSB) Radio Over The Air Updating to QR40.12 Software Version					
REFERENCE:	TSB: 08-025-24 GROUP: 08 - Electrical	Date:	January 24, 2024	REVISION:	-
VEHICLES	2021 (DJ) RAM 2500 Pickup 2021 (D2) RAM 3500 Pickup 2021 (DD) RAM 3500 Cab Chassis 2021 (DF) RAM 3500 10K LB. Cab Chassis			MARKET APPLICABILITY:	
AFFECTED:				\boxtimes NA	☐ MEA
				☐ SA	☐ IAP
				□ EE	□ СН
	2021 (DP) RAM 4500/5500 Cab Chassis 2021 (MP) Jeep Compass 2021 (WK) Jeep Grand Cherokee 2021 - 2023 (LA) Dodge Challenger 2021 - 2023 (LD) Dodge Charger 2021 - 2023 (LX) Chrysler 300 2021 - 2023 (BV) Jeep Renegade 2021 - 2023 (JL) Jeep Wrangler 2021 - 2023 (JL) Jeep Wrangler 2021 - 2023 (KL) Jeep Cherokee This bulletin applies to vehicles equipperadios: Uconnect 4C Nav With 8.4" Display R Uconnect 4C Nav With 8.4" Display R UCQ). Uconnect 4C With 8.4" Display Radio	Radio (Sales Radio (Sales	s Codes UAV or UCV). s Codes UAQ or		
CUSTOMER SYMPTOM:	 Customers may experience one or more of the following: Mobile Wi-Fi inoperative upon start up. Hotspot gives "No Internet" connection message on phone, when trying to connect to a device. 				

REPAIR SUMMARY:

Radio Software

CAUSE:

This bulletin provides information regarding the latest Firmware Over The Air (FOTA) update and provides the service technician an overview of the steps a customer will need to take to complete the update. The radio software will be updated from QR39.2 to QR40.11.

NOTE: National launch for this FOTA update is expected to begin February 19, 2023.

DISCUSSION:

Vehicles sold in the U.S. and Canada can now receive software updates "over-the-air". Updates to software will occur in a phased roll-out. The software is updated through the builtin cellular modem in the radio.

Customers will see a notification on their radio screen when new software is available for their radio Fig. 1. The owner will have the option to update the radio or schedule the update for later. **There is not an option to decline the update indefinitely, the update must be performed.**



Fig. 1
Software Acceptance Screen

NOTE: If selecting "Schedule Update" the screen below will be displayed. The customer can select the exact time they want the update to begin Fig. 2.



Fig. 2 Schedule Update Screen

- 1. The vehicles transmission needs to be in the "Park" position, or have the vehicle in "Neutral" with parking brake engaged if equipped with a manual transmission. The ignition needs to be in the off position.
- 2. Whether the customer selects "Update Now", or "Schedule Update" Fig. 2 and sets a time, they can shut off the vehicle and leave. The update will be completed automatically Fig. 3.

NOTE: This step may take several minutes to complete.




Fig. 3
Update In Progress Screen

3. Upon completion of update, the radio will display a confirmation message Fig. 4.



Fig. 4
Update Confirmation Screen

POLICY:

Information Only

This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of FCA US LLC.