

REFERENCE:	TSB: 21-008-24 GROUP: 21 - Transmission and Transfer Case	Date:	January 24, 2024	REVISION:	–
VEHICLES AFFECTED:	2023 (B1) Jeep Renegade This bulletin applies to vehicles built on or after November 01, 2022 (MDH 1101XX) and on or before December 01, 2023 (MDH 1201XX).			MARKET APPLICABILITY: <input type="checkbox"/> NA <input checked="" type="checkbox"/> MEA <input checked="" type="checkbox"/> SA <input type="checkbox"/> IAP <input type="checkbox"/> EE <input checked="" type="checkbox"/> CH	
CUSTOMER SYMPTOM:	No symptom for the customer. Product upgrade for TCM internal software improvements.				
CAUSE:	TCM software update.				

REPAIR SUMMARY:

This bulletin provides information regarding the latest software for the TCM and performing the TCM reprogramming.

SPECIAL TOOLS/EQUIPMENT:

Description	Ref. No.	Notes
wiTECH or Equivalent	–	–

DISCUSSION:

NOTE: Install a battery charger to ensure sufficient battery voltage is provided during the flash process.

NOTE: If this flash process is interrupted/aborted, the flash should be restarted.

1. Reprogram the TCM with the latest software. Detailed instructions for flashing control modules using the wiTECH Diagnostic Application are available by selecting the application’s “HELP” tab.
2. Clear any DTCs that may have been set in any modules due to reprogramming. The wiTECH application will automatically present all DTCs after the flash and allow them to be cleared.

POLICY:

Information Only

This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of FCA US LLC.