

Technical Service Bulletin (TSB)
Radio Over The Air Update from
LR34.51 to LR35.41 Software Version

REFERENCE:	TSB: 08-029-24 GROUP: 08 - Electrical	Date:	January 30, 2024	REVISION:	-
VEHICLES AFFECTED:	<p>2020 - 2021 (DF) RAM 3500 10k Lb. Cab Chassis 2020 - 2021 (DP) RAM 4500/5500 Cab Chassis 2020 - 2021 (DT) RAM 1500 Pickup 2020 - 2021 (DJ) RAM 2500 Pickup 2020 - 2021 (D2) RAM 3500 Pickup 2020 - 2021 (DD) RAM 3500 Cab Chassis This bulletin applies to vehicles equipped with Uconnect 12.0 with Navigation (Sales Codes UAX and UCX).</p>	MARKET APPLICABILITY:			
		<input checked="" type="checkbox"/> NA		<input type="checkbox"/> MEA	
		<input type="checkbox"/> SA		<input type="checkbox"/> IAP	
		<input type="checkbox"/> EE		<input type="checkbox"/> CH	
CUSTOMER SYMPTOM:	<p>Customer may experience one or more of the following:</p> <ul style="list-style-type: none"> • Mobile Wi-Fi inoperative upon start up. • Hotspot gives "No Internet" connection message on phone when trying to connect to a device. 				
CAUSE:	Radio Software.				

REPAIR SUMMARY:

This bulletin provides information regarding the latest Firmware Over The Air (FOTA) update and provides the service technician an overview of the steps a customer will need to take to complete the update. The radio software will be updated from LR34.51 to LR35.41.

NOTE: National launch for this FOTA update is expected to begin February 19, 2024.

DISCUSSION:

Vehicles sold in the U.S. and Canada can now receive software updates “over-the-air”. Updates to software will occur in a phased roll-out. The software is updated through a builtin cellular modem in the vehicle. Customers will see a notification on their radio screen when new software is available for their radio [Fig. 1](#). The owner will have the option to update the radio or schedule the update for later. There is not an option to decline the update indefinitely, the update must be performed.

NOTE: This is an Information Only Service Bulletin to inform the dealer how the FOTA update is performed. This document does not contain a LOP for reimbursement.

1. The vehicle needs to be in ‘Park’. The ignition needs to be in the off position.
2. If the customer selects “Update Now” they can shut off the vehicle and leave. The update will be completed automatically [Fig. 1](#).




Fig. 1
Software Acceptance Screen

NOTE: This step may take several minutes to complete.

3. Upon completion of update, the radio will display a confirmation message [Fig. 2](#).




Fig. 2
Software Update Confirmation Screen

POLICY:
Information Only

This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of FCA US LLC.