

**Subject: Engineering Information - Melted Burn Marks and/or Smoke Smell Coming from the Height Adjuster Motor Under the Front Row Seat**

*This EI has been revised to end the need for gathering information from the field. Please discard PIE0773A.*

Brand:	Model:	Model Year:		VIN Breakpoint:		Engine:	Transmission:	
		from	to	from	to			
Buick	Enclave	2022	2024	—	—	—	—	
Cadillac	XT4							
	XT5							
	XT6							
Chevrolet	Blazer							
	Cruze							2023
	Equinox							2024
	Malibu							
	Traverse							
GMC	Acadia							2023
	Terrain	2024						

If you encounter a vehicle with the above condition, refer to SI for further diagnosis.

<b>Version</b>	3
<b>Modified</b>	Released December 21, 2023 Revised January 16, 2024 – Added Engine RPO LFY for Traverse. Revised March 13, 2024 – Ended the need for gathering further information from the field.