



SSM 52311 2024 F-150 - DTC B15F0:15 Setting In The IPMA When A Diagnostic Self-Test Is Performed

Some 2024 F-150 vehicles may set diagnostic trouble code (DTC) B15F0:15 in the image processing module A (IPMA) when a diagnostic self-test is performed. This may be due to a IPMA communication error within a specified timeframe. DTC B15F0:15 does not affect vehicle durability with no effect on vehicle operation, and no additional diagnosis or service is required for this condition at this time. Inform customers that they can continue to drive the vehicle and engineering is currently working on a solution for this condition that is expected in Q2 2024. Replacement or reprogramming of the IPMA will not resolve this condition. Monitor OASIS for additional information and schedule service appointments for customers once the repair becomes available.