



SSM 52315 2024 F-150 - SYNC - Steering Wheel Voice Command Button Will Not Initiate A Phone Call

Some 2024 F-150 vehicles may exhibit an inoperative steering wheel voice command button when trying to make a phone call. This may be due to the accessory protocol interface module (APIM) software. Replacement or reprogramming of the APIM will not resolve this condition. Inform customers that engineering is currently working on a solution for this condition and will be released via Ford Power-Up software updates delivered over-the-air (OTA) expected in Q3 2024. Software will update automatically if vehicle connectivity is enabled in the vehicle's settings. Schedule a service visit for customers who have disabled vehicle connectivity or who report that they did not receive the update in Q3 2024. Monitor OASIS for additional information.