



SSM 52319 2024 F-150 - SYNC - Incorrect Parking Sensor Soft Button Illumination On The Vehicle's Center Display Screen

Some 2024 F-150 Lightning vehicles equipped with a 12 inch center display and all 2024 F-150 gas engine vehicles may exhibit incorrect illumination of the parking sensor soft button on the vehicle's center display screen. This may be due to the accessory protocol interface module (APIM) software. Replacement or reprogramming of the APIM will not resolve this condition. Inform customers that engineering is currently working on a solution for this condition and will be released via Ford Power-Up software updates delivered over-the-air (OTA) expected in Q3 2024. Software will update automatically if vehicle connectivity is enabled in the vehicle's settings. Schedule a service visit for customers who have disabled vehicle connectivity or who report that they did not receive the update in Q3 2024. Monitor OASIS for additional information.