



SSM 52327 2020-2022 Corsair - HUD - Blank HUD Screen After Programming

Some 2020-2022 Corsair vehicles equipped with a head-up display (HUD) may exhibit a blank HUD screen condition after programming the module. This may be due to the software level installed in the HUD module and does not affect the instrument panel cluster (IPC) display. To correct this condition, reprogram the HUD module using the latest software level of the Ford Diagnosis and Repair System (FDRS) scan tool. For claiming, use causal part 19G468 and applicable labor operation in Section 10 of the Service Labor Time Standards (SLTS) Manual.