


**SUBJECT: SERVICE ACTION: OBC REPLACEMENT (SA307)**

	GROUP <b>ELE</b>	MODEL <b>2016MY Soul EV (PS EV)</b>
	NUMBER <b>138</b>	DATE <b>September 2017</b>

**TECHNICAL SERVICE BULLETIN**


**SUBJECT: SERVICE ACTION: OBC REPLACEMENT (SA307)**

This bulletin provides the procedure to replace the On-Board Charger (OBC) on some 2016MY Soul EV (PS EV) vehicles, produced from January 16, 2015, with the OBC that was installed on or after January 16, 2015, which may exhibit a malfunction indicator light (MIL) or Diagnostic Trouble Code (DTC) P1CF5 or P1CF6 due to a battery charge delay with the OBC. This issue is not related to the OBC that was installed on or after January 16, 2015. Related DTCs are P1CF5 and P1CF6. Before performing this procedure, verify that the vehicle is included in the list of affected VINs.

**ELE138/SA307**

DTC	Description
P1CF5	MIL Check
P1CF6	MIL Check

**CLOSED**



**\* NOTICE**

**A Service Action is a repair program without customer notification that is performed during the warranty period. Any dealer requesting to perform this repair outside the warranty period will require DPSM approval.**

**Repair status for a VIN is provided on WebDCS (Service → Warranty Coverage → Warranty Coverage Inquiry → Campaign Information). Not completed Recall / Service Action reports are available on WebDCS (Consumer Affairs → Not Completed Recall → Recall VIN → Select Report), which includes a list of affected vehicles.**

**This issue number is SA307.**