


SUBJECT: SERVICE ACTION: OBC UPDATE, INSPECTION AND/OR REPLACEMENT (SA306)

	GROUP ELE	MODEL 2015-17MY Soul EV (PS EV)
	NUMBER 137	DATE October 2017

TECHNICAL SERVICE BULLETIN

SUBJECT: SERVICE ACTION: OBC UPDATE, INSPECTION AND/OR REPLACEMENT (SA306)

This bulletin provides the procedure to update, inspect, and if necessary, replace the On-Board Charger (OBC) on some 2015-17MY Soul EV (PS EV) vehicles, produced from July 2014 through January 15, 2017, which may exhibit a Malfunction Indicator Lamp (MIL) and Diagnostic Trouble Codes (DTCs) P1CF1 through P1CF6. This may be due to a battery charge delay. To address this concern, follow the procedure outlined in this bulletin. Refer to the list of affected vehicles to verify that the vehicle is included in the list of affected vehicles.

DTCs:

- P1CF1 – HV DC Interlock Fault
- P1CF2 – HV DC Interlock Charge
- P1CF3 – HV DC Interlock Discharge
- P1CF4 – HV DC Interlock Precharge
- P1CF5 – HV DC Interlock Precharge
- P1CF6 – HV DC Interlock Precharge

ELE137/SA306
CLOSED



*** NOTICE**

A Service Action is a repair program without customer notification that is performed during the warranty period. Any dealer requesting to perform this repair outside the warranty period will require DPSM approval.

Repair status for a VIN is provided on WebDCS (Service → Warranty Coverage → Warranty Coverage Inquiry → Campaign Information). Not completed Recall / Service Action reports are available on WebDCS (Consumer Affairs → Not Completed Recall → Recall VIN → Select Report), which includes a list of affected vehicles.

This issue number is SA306.