


Drivers Information Display (DID) Inoperative After Cluster Replacement And Programming

Published Date March 2024

Valid For

Mack AN,GR,CHU,CXU,PI and Volvo VNR,VNR,VNX,VHU,VHD Model Year 2021 to Current

After cluster replacement and programming, the Driver Information Display (DID) may not function as designed. See Image below.



If that occurs, follow these steps:

1. Disconnect the low voltage batteries for 10 minutes.
2. Reconnect the low voltage batteries.

The full power cycle should fix the issue.

If the issue persists, please contact Tech Support.

Related links and attachments

No links or attachments available



Share

to others that might find it helpful



Feedback

[Give feedback](#)

to help improve the content of this
article