

WRC4 Stop Delivery - Checking the fuel filler flap / charging flap and rework if necessary

WRC4 Stop Delivery - Checking the fuel filler flap / charging flap and rework if necessary

ID Number	WRC4
Models	Panamera (YAA / YAB)
Model Years	2024
VIN List	Attached
Number of Affected VINs	1,621
Issue Description	<p>On the affected vehicles, it is possible that the fuel filler flap / charging flap (PHEV) may absorb moisture under certain conditions due to the material characteristics.</p> <p>This can lead to deformation of the fuel filler flap or charging flap when the vehicle is parked for long periods at low temperatures in combination with high humidity and can be perceived by the customer as a visual complaint in the form of a protrusion of the fuel filler flap/charging flap.</p> <p>For this reason, the fuel filler/charging flap must be checked and, if necessary, removed and dried before delivery to the customer.</p>
What should Porsche Centers do?	<p>Please do not deliver the subject vehicles until the repair is completed.</p> <p>As of the time of this posting (3/21/24) the repair is immediately available.</p>
TI Number	No. 39-24

Attachments

- [1. VIN_List_Report_WRC4_2024-03-28_V2.xlsx](#)