

# WRC5 Stop Delivery - Check main wire harness in luggage compartment and rework if necessary

---

## WRC5 Stop Delivery - Check main wire harness in luggage compartment and rework if necessary

ID Number	WRC5
Models	Panamera (YAA / YAB)
Model Years	2024
VIN List	Attached
Number of Affected VINs	642
Issue Description	<p>Due to a process error during assembly, it is possible that the main wiring harness in the luggage compartment of the affected vehicles was not installed in accordance with the specifications.</p> <p>If this is the case, damage to the main wiring harness cannot be ruled out.</p> <p>For this reason, the main wiring harness in the luggage compartment must be checked before delivery and reworked if necessary.</p>
What should Porsche Centers do?	<p>Please do not deliver the subject vehicles until the repair is completed.</p> <p><b>As of the time of this posting (3/20/2024) the repair is immediately available</b></p>
Technical Information	<a href="#">No. 44-24</a>

---

### Attachments

- 1. [VIN\\_List\\_Report\\_WRC5\\_2024-03-19\\_V2.xlsx](#)
- 2. [WRC5\\_Remedial measure\\_EN\\_V2.pdf](#)