

RECALL H414/N808 – POWERTRAIN CONTROL MODULE (PCM) UPDATE

EMISSIONS RECALL H414/N808 – POWERTRAIN CONTROL MODULE (PCM) UPDATE – DIESEL ONLY

AFFECTED MODELS	17-18MY Range Rover, Range Rover Sport, Discovery 18-19MY Range Rover Velar 17-19MY F-PACE, XE, XF
VOLUME AFFECTED	JAG 7,299 US 1,909 CAN LR 10,374 US 3,098 CAN
REPAIR	A concern has been identified where on certain vehicles equipped with TDV6 3.0L Diesel and Ingenium I4 2.0L Diesel engines, when connected to a diagnostic scan tool during the California SMOG test, the Powertrain Control Module (PCM) incorrectly reports the monitor readiness status as 'not supported'. A software update to the PCM is needed.
REPAIR TIME	0.2 hrs. + DIDO
CAMPAIGN LAUNCH	Previously launched as a customer satisfaction program, these were re-published on February 26 th as Emissions recalls.
NOTES	Please refer to the warranty portal for affected vehicles and in BBSS to identify the affected vehicles in retailer inventory which must not be sold or delivered until repaired. Sold vehicles must be repaired at the next service visit Clients were notified via mail March 6 th , 2024.