

Document Title:	Repair of the Murphy Bed Latch		
Document Type:	Technical Service Bulletin	Make and Model:	Ember Overland and Touring Series
Document #:	23-02	Model Year:	2022 and 2023
Release Date:	August 8, 2023	Flat Rate:	Code: 50000190 0.5 Hours
Pre-Auth Required:	No	Pictures Required:	Yes, before and after repair

Material List		
Item Index	Ember Part Number	Description/Material Type
1	95000415	METAL STRIKE PLATE MURPHY LATCH 1/4" THICK

I. Purpose

To provide instructions on how to repair the murphy bed latch when identified to not latch securely on the Overland and Touring edition travel trailers.

II. Procedure

1. Remove the silver strike plate for the murphy bed latch.



2. Place item 95000415, METAL STRIKE PLATE MURPHY LATCH 1/4" THICK behind the silver strike plate and secure as shown below:



3. Verify murphy bed latches securely.
4. Submit a warranty claim with before and after pictures of the repair. Before and after pictures are required for claim approval.

Maintenance Recommendations/Other

Safety, education, and customer satisfaction are our primary concerns. Should you have any questions, please contact us at 844-732-4204 or by email at warranty@emberrv.com.