

Preliminary Information

PIT6038A Remote Vehicle Start Inoperative, No Response To Fob

Models

Brand:	Model:	Model Years:	VIN:		Engine	Transmissions:
			from	to	Engine:	Hansinissions.
Chevrolet	Colorado	2023 - 2024	All	All	All	All
GMC	Canyon	2023 - 2024	All	All	All	All

Involved Region or Country:	North America		
RPOs	-BTV / +S6P		
Condition:	Remote start inoperative, usually found at PDI.		
Cause:	BCM has not been updated with the correct software.		

Vehicles built without RPO BTV - Remote Vehicle Start but are optioned with RPO S6P - Dealer Installed Remote Vehicle Start will require a BCM calibration update from TCSC to activate the function. Contact TCSC at 800-828-6860 for programming assistance.

Version History

Version	2		
Modified	06/30/2023 - Created on.		
Modified	03/20/2024 - Added 2024 Model Year.		

















GENERAL MOTORS

 $\hbox{@ 2024 General Motors. All Rights Reserved.}$