



Preliminary Information

PIT6141 Check Ball and Cap Location When Replacing Power Brake Booster or Power Brake Booster Pump


Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Chevrolet	Silverado 4500HD, 5500HD, 6500HD	2019 - 2023	All	All	All	All

Involved Region or Country	North America
Condition	A technician may find a check ball and plastic cap that separated from the brake booster pump motor when the pump is separated from the booster.
Cause	The cap and check ball may have pulled out of the pump motor when it was separated from the brake booster (possibly falling on the ground.)

Correction:

Insert check ball (1) and cap (2) into rear most port (towards brake pedal push rod on brake booster) as shown below:



Version History

Version	1
Modified	03/22/2024 - Created on.



GENERAL MOTORS

© 2024 General Motors. All Rights Reserved.