



Bulletin No.: PIT6143
Published date: 03/25/2024

Preliminary Information

PIT6143 LPO Installed Tire Makes Contact With Vehicle

Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Chevrolet	Colorado	2024	All	All	All	All

Involved Region or Country:	North America
Additional RPOS	QXP, QAE
Condition:	Some customers may have a concern where the LPO installed tires will make contact with the vehicle.
Cause:	The incorrect LPO tires may have been installed.

Correction:

Check the installed tire size against the tire/wheel placard on the vehicle and in IVH. If the installed tire size is different the correct tire size needs to be installed. Order the correct tire size per the placard and replace as necessary.

Warranty Information

For vehicles repaired under the Bumper-to-Bumper coverage (Canada Base Warranty coverage), use the following labor operation. Reference the Applicable Warranties section of Investigate Vehicle History (IVH) for coverage information.

Labor Operation	Labor Operation Description	Labor Time
8086018	Tire Replacement	1.3 Hrs.

Version History

Version	1
Modified	03/25/2024 - Created on.



G E N E R A L M O T O R S

© 2024 General Motors. All Rights Reserved.