

Subject

Torque Converter Installation Precaution

Market

USA

Service Category

Drivetrain

Section

Automatic Transmission/Transaxle

Applicability

23-24Sequoia HV 22-24Tundra/Tundra HV

APPLICABLE VEHICLES

2022-2024	Tundra	2023-2024	Sequoia HV
2022-2024	Tundra HV		


CONDITION

During repairs such as those listed below, damage may occur if the Torque Converter Assembly is not properly installed.

- Hybrid module assembly removal/installation
- Transmission removal/installation
- Engine removal/installation

RECOMMENDATIONS

Referring to the appropriate Repair Manual Installation instructions, pay close attention to step #2 for Torque Converter Assembly Installation. It is critical to align the oil pump drive sprocket at the "12-6" o'clock position as indicated in the diagram below **before** installing the Torque Converter cutout to the protrusion on the oil pump.



Subject

Torque Converter Installation Precaution

Market

USA

Applicability

LINK REFERENCES

1. [L4A0E \(HYBRID TRANSMISSION / TRANSAXLE\): HYBRID VEHICLE TRANSMISSION: INSTALLATION; 2023 - 2024 MY Sequoia HV \[09/2022 - ???????\]](#)
2. [L4A0F \(HYBRID TRANSMISSION / TRANSAXLE\): HYBRID VEHICLE TRANSMISSION: INSTALLATION; 2023 - 2024 MY Sequoia HV \[09/2022 - ???????\]](#)
3. [AJA0E \(AUTOMATIC TRANSMISSION / TRANSAXLE\): AUTOMATIC TRANSMISSION ASSEMBLY: INSTALLATION; 2022 - 2024 MY Tundra \[11/2021 - ???????\]](#)
4. [AJA0F \(AUTOMATIC TRANSMISSION / TRANSAXLE\): AUTOMATIC TRANSMISSION ASSEMBLY: INSTALLATION; 2022 - 2024 MY Tundra \[11/2021 - ???????\]](#)
5. [L4A0E \(HYBRID TRANSMISSION / TRANSAXLE\): HYBRID VEHICLE TRANSMISSION: INSTALLATION; 2022 - 2024 MY Tundra Tundra HV \[05/2022 - ???????\]](#)